

LAKE COUNTY

Lake County Project No. 20111454 ADA Self-Evaluation and Transition Plan



Eric Contreras, Assoc. AIA, CGC AADAG Consulting Services, LLC (ACS) LEED AP® Architecture–Engineering-Construction Miami-New York-New Orleans-Dallas-Los Angeles Toll Free: 1(888) 768-7788 E-mail: econtreras@adaag-consulting.com www.adaag-consulting.com Fred Schneider, P.E., PTOE Director of Engineering Lake County Public Works 437 Ardice Ave. Eustis, FL 32726 T. (352) 483-9040 E-mail: FSchneider@lakecountyfl.gov

Outline



- **1. INTRODUCTION**
- 2. BACKGROUND
- **3. TITLE II REQUIREMENTS**
- 4. SCOPE OF WORK
- **5. PUBLIC INFORMATION MEETING**
- 6. ACTIONS
- 7. CONTACT INFORMATION
- 8. QUESTIONS AND ANSWERS

1. Introduction



ADAAG CONSULTING SERVICES, LLC

- Lake County committed to making its programs and services accessible to persons with disabilities implements ADA Transition Plan for PROW
- ACS A/E firm incorporated in 1995, headquarters in Miami, offices in Dallas, Los Angeles, Louisiana & New York
- Expertise in accessibility consulting with over 380 million SF of accessibility assessment & Section 504/ ADA Title II Transition Plan Development
- Accessibility committees: ICC, Access Board, NAAC, Accessibility Advisor Council for Constructions Boards.

2. Background



- Originated from the 1964 Civil Rights Act.
- Architectural Barriers Act of 1968 accessibility standards for buildings & facilities.
- Section 504, Rehabilitation Act of 1973 prohibits discrimination in federally assisted programs.
- Title I & II Americans with Disabilities Act ("ADA") -7/26/90.
- ADA/ABA Accessibility Guidelines 7/23-04, amended 8/5/05.
- FHWA Memo 1/23/06 DRAFT Guidelines "best practices".
- Proposed Accessibility Guidelines PROW 11/23/11
- FDOT standards and specifications.

3. Title II Requirements



- **Requirements, Guidelines, Regulations & Checklist**
- Self-evaluation
- ADA Coordinator
- Adoption of a grievance procedure
- Prohibition against discrimination
- Requirements for New construction, alterations, existing construction, historic facilities
- Transition Plan
- Curb ramps at newly constructed streets
- Priorities

3. ADA Transition Plan Requirements




- Identify physical obstacles
- Describe methods
- Specify the schedule
- Indicate official responsible



3. Title II Compliance





©1992 Adaptive Environments Center. Produced under contract to Barrier Free Environments, NIDRR grant #H133D10122

3. Steps for Compliance



PHASE I: COMMITMENT

Agency Head or Department Director demonstrates a commitment to Access Compliance.

PHASE II: SELF-EVALUATION

Complete Self-Evaluation and develop Transition Plan to identify and resolve accessibility issues.

PHASE III: TRANSITION

Prepare budget and correction plan to submit to Department of Finance (DOF) for approval.

PHASE IV: IMPLEMENTATION

Implement all items in the Self-Evaluation and remove structural noncompliance items of the Transition Plan.

PHASE V: ONGOING SUPPORT

Continue involvement and resolution of all problems and issues related to ADA. Provide periodic assessment related to the proper maintenance of all access features.





- Physically inspect Lake County's public rights-ofway (90 miles Collector Roads)
- Determine existing conditions and barriers to access
- Develop a comprehensive Transition Plan
- Perform public information meeting.

5. Lake County Public Information Meeting



- Notify of Transition Plan Development (organizations)
- Information of requirements
- Notify of personnel involved, process and schedule
- Establish communication to address concerns regarding PRW
- Gather input from disabled community and interested groups

5. Lake County Public Information

- Notify of Transition Plan Development (organizations):
 Sunrise Arc
 - Center for Independent Living of Central Florida
 - Center for Independent Living of North Central Florida
 - Disability Solution for Independent Living, Inc.
 - Protection & Advocacy Disability Rights Florida
 - Florida Association of the Deaf
 - Children's Advocacy Center
 - -VFW
 - Disabled American Veterans
 - Florida Department of Transportation
 - Federal Highway Administration

6. Actions PROW ADA Transition Plan – Lake County Scope of Work


Physically inspect Lake County's public rights-of-way (90 miles Collector Roads)

cgiD	City	Departme	Length	Left_Sidew	Right_Curb	Right_Side	Route	Route_Ahea	Route_Back	Travel_Dir
1-3047-05	Astatula	MA1	116 ft	Concrete	None	None	CR 561 (3047)	Ohio Av	Maryland Av	North
1-3047-06	Astatula	MA1	223 ft	Concrete	None	None	CR 561 (3047)	CR 48 (3056)	Ohio St	North
1-3047-07	Astatula	MA1	216 ft	Concrete	None	None	CR 561 (3047)	South Carolina Av	CR 48 (3056)	North
1-3047-08	Astatula	MA1	1413 ft	Concrete	None	None	CR 561 (3047)	Palm Dr (3046)	CR 48 (3056)	North
1-3047-20	Unincorporated	MA1	301 ft	Concrete	None	None	CR 561 (3047)	Lane Park Cutoff (3444)	CR 448 (3156)	North
1-3047-21	Unincorporated	MA1	604 ft	Concrete	None	Concrete	CR 561 (3047)	Lane Park Cutoff (3444)	CR 448 (3156)	North
1-3047-22	Unincorporated	MA1	270 ft	Concrete	None	None	CR 561 (3047)	Lake Idamere By	CR 448 (3156)	North
1-3047-29	Unincorporated	MA1	291 ft	Concrete	None	None	CR 561 (3047)	SR 19	SOUTH DORA BV	North
1-3056-06	Astatula	MA1	71 ft	None	None	Concrete	CR 48 (3056)	North Van Buren St	ALAMANDA DR	west
1-3056-07	Astatula	MA1	80 ft	Concrete	None	Concrete	CR 48 (3056)	North Van Buren St	ALAMANDA DR	west
1-3056-08	Astatula	MA1	588 ft	Concrete	None	Concrete	CR 48 (3056)	North Van Buren St	HARRISON ST	west
1-3056-09	Astatula	MA1	943 ft	Concrete	None	Concrete	CR 48 (3056)	North Van Buren St	HARRISON ST	west
1-3056-10	Astatula	MA1	77 ft	Concrete	None	Concrete	CR 48 (3056)	Jackson St	HARRISON ST	west
1-3056-11	Astatula	MA1	120 ft	Concrete	None	Concrete	CR 48 (3056)	CR 561 (3047)	North Van Buren St	west
1-3056-12	Astatula	MA1	82 ft	Concrete	None	Concrete	CR 48 (3056)	CR 561 (3047)	Jackson St	west
1-3056-13	Astatula	MA1	1655 ft	Concrete	Type F	Concrete	CR 48 (3056)	CR 561 (3047)	Jackson St	west
1-3156-01	Unincorporated	MA1	26 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-02	Unincorporated	MA1	440 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-03	Unincorporated	MA1	850 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-04	Unincorporated	MA1	232 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-05	Unincorporated	MA1	572 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-06	Unincorporated	MA1	483 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-07	Unincorporated	MA1	94 ft	Concrete	None	None	CR 448 (3156)	CR 561 (3047)	SR 19	East
1-3156-15	Unincorporated	MA1	1668 ft	None	None	Concrete	CR 448 (3156)	Southridge Industrial Dr	CR 561 (3047)	East
1-3156-17	Unincorporated	MA1	248 ft	Concrete	None	None	CR 448 (3156)	Southridge Industrial Dr	CR 561 (3047)	East
1-3156-18	Unincorporated	MA1	590 ft	Concrete	None	Concrete	CR 448 (3156)	Southridge Industrial Dr	CR 561 (3047)	East
1-3156-19	Unincorporated	MA1	105 ft	Concrete	None	None	CR 448 (3156)	Lake Industrial Bv (3349)	Southridge Industrial D	East
1-3156-20	Unincorporated	MA1	220 ft	Concrete	None	None	CR 448 (3156)	Lake Industrial Bv (3349)	Southridge Industrial D	East
1-4122-02	Unincorporated	MA1	741 ft	None	None	Concrete	Sunnyside Dr (4122)	Sunnyside Dr (4122)	SR 44	East
1-4140-04	Unincorporated	MA1	188 ft	Concrete	None	None	Dead River Rd (4140)	Baytree Bv	Marsh Harbor Dr	South
1-4140-05	Unincorporated	MA1	95 ft	Concrete	None	None	Dead River Rd (4140)	CAPTAIN HAYNES RD	Baytree Bv	South
1-4140-05	Unincorporated	MA1	228 ft	None	None	Concrete	Dead River Rd (4140)	CAPTAIN HAYNES RD	Fox Run By	South
1-4140-07	Unincorporated	MA1	158 ft	None	None	Concrete	Dead River Rd (4140)	CAPTAIN HAYNES RD	Fox Run By	South
1-4140-08	Unincorporated	MA1	1383 ft	None	None	Concrete	Dead River Rd (4140)	Woodview Dr	CAPTAIN HAYNES RD	South
1-4410-11	Leesburg	MA1	201 ft	Concrete	Type F	None	Main St (4410)	Chester St	TRUETT ST	East
1-4410-12	Leesburg	MA1	160 ft	Concrete	Type F	Concrete	Main St (4410)	US 27	Chester St	East
1-4410-13	Leesburg	MA1	115 ft	Concrete	Type F	Concrete	Main St (4410)	US 27	15TH St	East
1-4410-14	Leesburg	MA1	122 ft	Concrete	Type F	Concrete	Main St (4410)	US 27	15TH St	East
1-4410-15	Leesburg	MA1	102 ft	Concrete	Type F	Concrete	Main St (4410)	OAK Av	US 27	East
1-4410-16	Leesburg	MA1	23 ft	Concrete	Type F	Concrete	Main St (4410)	13TH St	OAK Av	East
1-4410-17	Leesburg	MA1	231 ft	Concrete	Type D	Concrete	Main St (4410)	9th St	OAK Av	East
1-4410-18	Leesburg	MA1	101 ft	Concrete	Type F	Concrete	Main St (4410)	9th St	North Lee St	East
1-4410-19	Leesburg	MA1	1180 ft	Concrete	Type F	Concrete	Main St (4410)	Orange Av	9th St	East
1-4410-20	Leesburg	MA1	301 ft	Concrete	Type F	Concrete	Main St (4410)	Orange Av	9th St	East
1-4410-21	Leesburg	MA1	263 ft	Concrete	Type F	Concrete	Main St (4410)	Orange Av	9th St	East
1-4410-22	Leesburg	MA1	765 ft	Concrete	Type F	Concrete	Main St (4410)	Orange Av	9th St	East
1-4410-23	Leesburg	MA1	62 ft	Concrete	Type F	Concrete	Main St (4410)	7TH ST	9th St	East
1-4410-24	Leesburg	MA1	301 ft	Concrete	Type F	Concrete	Main St (4410)	7TH ST	Orange Av	East
1-4410-25	Leesburg	MA1	60 ft	Concrete	Type F	Concrete	Main St (4410)	7TH ST	Orange Av	East

6. Actions - PROW ADA Transition Plan - Lake County Map



- Lake County Map
 - Astatula
 - Clermont
 - Eustis
 - Fruitland
 - Groveland
 - Howey-in-theHills
 - Lady lake
 - Leesburg
 - Mascote
 - Mineola
 - Montverde
 - Mount Dora
 - Tavares
 - Umatilla



6. Actions - PROW ADA Transition

ID	cgID	City	Dept	Curb Ramp Type	Location	Route	Route Ahead /Cross Street	Route Back /End Street Back	Corner	Side	Deficiency	Code	Proposed Correction	Priority	Cost	Photo	Point X	Point Y
FL069MTDCR0006		Mount Dora	<nul></nul>	No Curb Ramp	Intersection	OLD 441	LUCERNE DR		sw	s	Sidewalk does not have a curb ramp where accessible route crosses curb.	§4.7	Rework sidewalk providing a curb ramp with a 8.33% max, running slope that does not project into vehicular traffic lanes (ADAAG Fig. 15).	2		20111207_1 01202.jpg	442627.373	1626848.699
FL069MTDCR0007		Mount Dora	<nul></nul>	No Curb Ramp	Intersection	OLD 441	LUCERNE DR		SE	s	Sidewalk does not have a curb ramp where accessible route crosses curb.	§4.7	Rework sidewalk providing a curb ramp with a 8,33% max, running slope that does not project into vehicular traffic lanes (ADAAG Fig. 15).	2		20111207_1 01312.jpg	442675.979	1626818.245
FL069MTDCR000B	3-0500A-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	Transition at the bottom landing to the walloway is not flush and/or free of abrut changes	§4.5	Rework area and provide a transition to the walkway at the bottom flush and free of abrupt changes (ADAAG Fig. 7 c, d).	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR000B	3-05004-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	The surface of the curb ramp is unstable and has loose material.	§4.5	Rework and clean curb ramp to provide a stable, firm, and slip-resistant floor surface	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR0008	3-05004-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	Surface does not have truncated domes or detectable warnings.	§4.29	Rework surface providing raised truncated domes with a diameter of normial 0.9° (22 nm), a height of 0.2° (5 mm) and a center-to-center spacing of normial 2.35° (59 nm) and shall contrast visually with adjoining surfaces.	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR0008	3-05004-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	The transition at the bottom has a 26% non-compliant slope	§4.7	rework ore root or one carb ramp providing it flush with a moderate gutter counter slope (no more than 5%) for a wheelbase distance (24" [610 mm] from the curb)	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR0008	3-0500A-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	The surface of the curb ramp is unstable and has loose material.	§4.5	Rework and clean curb ramp to provide a stable, firm, and slip-resistant floor surface.	2		20111207_1 02237.jpg	443331.444	1626845.23
FLDG9MTDCR000B	3-0500A-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	Perpendincular Curb Ramp has a 3° change in level.	§4.5	Rework area and provide a 0.5" (12 mm) max. change of level, beveled with a sixpe no greater than 1:2 or mitigate condition by means of a cub ramp, ramp or platform lift (ADAAG Fig. 7 c, d).	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR0008	3-05004-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE DR		NE	N	Transition at the top landing to the walkway is not flush and/or free of abrut changes	§ 4.5	Rework area and provide a transition to the walkway flush and free of abrupt changes (ADAAG Fig. 7 c, d).	2		20111207_1 02237.jpg	443331.444	1626845.23
FL069MTDCR0008	3-0500A-54	Mount Dora	<nul></nul>	Perpendin cular	Intersection	OLD 441	MORNINGSIDE		NE	N	Curb ramp has a 14.25% non- compliant running slope.	§4.7	Rework curb ramp to provide a running slope not to exceed 8,33%.	2		20111207_1 02237.ipg	443331.444	1626845.23
FL069MTDCR0010	3-0500A-55	Mount Dora	<nul></nul>	No Curb Ramp	Intersection	OLD 441	HEIM RD		NE	N	Sidewalk does not have a curb ramp where accessible route crosses curb.	§ 4.7	Rework sidewalk providing a curb ramp with a 8.33% max. running slope that does not project into vehicular traffic lanes (ADAAG Fig. 15).	2		20111207_1 03522.jpg	444868.141	1626710.566
FL069MTDCR0076		Mount Dora	<nuil></nuil>	No Curb Ramp	Intersection	OLD 441	POINSETTIA DR		ĸw	N	Sidewalk does not have a curb ramp where accessible route crosses curb.	§4.7	Rework sidewalk providing a curb ramp with a 8.33% max, running slope that does not project into vehicular traffic lanes (ADAAS Fig. 15).	2		20111207_0 95607.jpg	441272.09	1626966.502
FL069MTDCR0077		Mount Dora	<nul></nul>	No Curb Ramp	Intersection	OLD 441	POINSETTIA DR		NE	N	Sidewalk does not have a curb ramp where accessible route crosses curb.	§4.7	Rework sidewalk providing a curb ramp with a 8.33% max. running slope that does not project into vehicular traffic lanes (ADAAG Fig. 15).	2		20111207_0 95732.jpg	441343.963	1626967.115

6. Actions - PROW ADA Transition Plan – Sidewalk Rating



LAKE CO	DUNT	Y Side	ewalks (Condition	1									
ID	CITY	DEPT	ROUTE	ROUTE AHEAD	ROUTE BACK	LOC	CORNER	SIDE	SIDEWALK	SIDEWALK CONDITION	Photo	cg ID	POINT X	POINT Y
FL069ASTSW0001	Astatula		CR 561	OHIO ST	MASSACHUSETTS	Farment		w	Concrete	4. COMPLIANT 0-24% or more in bed	20112224 124210 000	1.0047.04	421108.251	1591218.539
FL069ASTSW0002	Constraint.		01.301	ONUO SI	AVF	Segment		**	Concrete	condition	20111024_134510.jpg	1-304/-08	421100.251	1391210.339
	Astatula		CR 561	MASSACHUSETTS AVE	KANSAS AVE	Segment		w	Concrete	4. COMPLIANT 0-24% or more in bed	20111024_135155.jpg	1-3047-05	421100.5007	1590786.963
FL069ASTSW0003										condition				
	Astatula		CR 561	KANSAS AVE	TENNESSEE AVE	Segment		w	Concrete	 COMPLIANT 0-24% or more in bad condition. 	20111024_135914.jpg	1-3047-05	421100.3127	1589650.886
FL069ASTSW0004	Astatula		CR 561	TENNESSEE AVE	MARYLAND AVE	Segment		w	Concrete	4. COMPLIANT 0-24% or more in bad	20111024_141229.jpg	1-3047-05	421102.8651	1589565.419
FL069ASTSW0005										condition.				
	Astatula		CR 48	CR 561	JACKSON ST	Segment		N	Concrete	4. COMPLIANT 0-24% or more in bad condition	20111024_143112.jpg	1-3056-11	421830.5481	1591595.077
FL069ASTSW0006	Astatula		CR 48	VAN BUREN ST	HARRISON ST	Segment		N	Concrete	4. COMPLIANT 0-24% or more in bed	20111024 144555 Inc	1-3056-07	422928.4183	1591578.363
FL059ASTSW0007										condition				
	Astatula		CR 48	ALAMANDA DR	RANCH RD	Segment		N	No Sidewalk	0. NO SIDEWALK	20111024_150555.jpg		424025.3232	1591584.902
FL069ASTSW0008	A state in		<i>(1) (2)</i>	LACONCAL OF		£			fun make	A COMPLEXITY OF AND ADDRESS IN AND				1001000.010
FL069ASTSW0009	Astatula		CR 48	JACKSON ST	VAN BUREN ST	Segment		N	Concrete	4. COMPLIANT 0-24% or more in bed condition	20111024_150916.jpg	1-3056-11	422105.7901	1591582.915
100000010100000	Astatula		CR 561	FLORIDA AVE	OHIO ST	Segment		w	Concrete	3. GOOD. 25-49% or more in bed		1-3047-06	421108.3543	1591508.754
FL069ASTSW0010										condition				
	Astatula		CR 561	OHIO ST	MASSACHUSETTS AVE	Segment		w	Concrete	 GOOD. 25-49% or more in bed condition. 	20111024_134938.jpg	1-3047-05	421091.3711	1590960.214
FL069A5T5W0011	Astatula		CR 561	MARYLAND AVE	TENNESSEE AVE	Segment		w	Concrete	3. GOOD. 25-49% or more in bed	20111024_141015.jpg	1-3047-05	421126.8257	1589988.415
FL069ASTSW0012										condition.				
	Astatula		CR 48	CR 561	JACKSON ST	Segment		s	Concrete	 COMPLIANT 0-24% or more in bed condition. 	20111024_142959.jpg	1-3056-11	421802.0255	1591518.09
FL069A5T5W0013	Astatula		CR 48	VAN BUREN ST	HARRISON ST	Segment		s	Concrete	4. COMPLIANT 0-24% or more in bad	20111024 144401 (m)	1-3056-02	423142-0136	1591504.009
FL069A5TSW0014	00.000		CK 40	the contra	in the second se	Jayman		-	CONCIENT	condition	2011/02-CTHIOL-JPG	1-3030-07	1231123130	1391304.009
	Astatula		CR 48	HARRISON ST	RANCH DR	Segment		5	Concrete	4. COMPLIANT 0-24% or more in bad condition	20111024_145227.jpg		423832.1435	1591518.753
FL069A5T5W0015														
	Astatula		CR 561	TENNESSEE AVE	COUNTRY CLUB DR	Segment		E	No Sidewalk	0. NO SIDEWALK	20120405_140611.jpg	1-3047-05	421139.3762	1589627.265
FL069ASTSW0016	Astatula		CR 561	MEDWAY AVE	COUNTRY CLUB DR	Segment		w	No Sidewalk	0. NO SIDEWALK	20120405_142428.jpg	1-3047-05	421117.684	1592638.007
FL069CLESW0001														
	Clermont		CR 561	LAKE MINNEOLA DR	SR 50	Segment		E	No Sidewalk	0. NO SIDEWALK	20111025_084918.jpg	2-1733-30	407121.6467	1537104.56
FL059CLESW0002	Clermont		CR 561	W OSCEOLA ST	W MONTROSE ST	Segment		w	Concrete	3. 9000. 25-49% or more in bed	20111025_085845.jpg	2,1733,30	407167.6528	1536113.538
FL059CLESW0003	Capital				11	cognon			0.010	condition.			10.001.001.0	
	Clermont		CR 561	EMERALD LAKES DR	CHESTNUT ST	Segment		w	Concrete	4. COMPLIANT 0-24% or more in bad condition.	20111025_092448.jpg	2-0634-06	407149.9472	1533719.059
FL059CLESW0004														
	Clermont		CR 561	SEMINOLE ST	W MINNEHAHA AVE	segment		w	Concrete	4. COMPLIANT 0-24% or more in bed	20111025_100230.jpg	2-0634-06	407137.2763	1532390.941

6. Actions Subdivision – Self-Evaluation



- Lake County performed a self-evaluation of sidewalks along subdivisions 10 years or older
- Inventory of barriers to access
- D3 Maintenance areas
- Surface
- Changes in level

6. Actions Subdivision – Self-**Evaluation**



			SIDEWALK REPAIR I	NVENTO	DRY		
			MAINTENANCE	AREA II			
DATE	SUBDIVISION	PICTURE #	LOCATION	L (ft)	W (ft)	PROBLEM	NOTES/SOLUTION
09/30/10	Greater Pines	1	across street from 14852			1" Lift -corner	
			Greater Pines Bv				
09/30/10	Greater Pines	2	across street from 14742			1/2" lift-depression	
			Greater Pines Bv				
09/30/10	Greater Pines	3	Corner of Lobiolly Ln and			1/2" lift-depression	
			Greater Pines Bv(by fiber optic	:			
			marker)				
09/30/10	Greater Pines	4	14715 Greater Pines Bv (by			Broken corner- hole	
			light pole)				
09/30/10	Greater Pines	5	14651 Greater Pines Bv			1/4" Lift	
09/30/10	Greater Pines	6	14651 Greater Pines Bv (by			1/4" Lift- depression corner	-
			phone box)				
09/30/10	Greater Pines	7	14635 Greater Pines Bv	12"		Broken driveway -corner	
09/30/10	Greater Pines	8	14617 Greater Pines Bv			1/4" Lift-corners	
09/30/10	Greater Pines	9	14549 Greater Pines Bv(by			1/4" Lift	
			water meter)				
09/30/10	Greater Pines	10	14549 Greater Pines Bv	4'		Cracked- Broken side-hole	
09/30/10	Greater Pines	11	14549 Greater Pines Bv(by			1/4" Lift- depression	
			light pole)				
09/30/10	Greater Pines	12	14501 Greater Pines Bv (by			1/2" lift- depression	
			light pole)				
09/30/10	Greater Pines	13	comer of Long Pine Tr and			1/2" Lift-corner	
			Greater Pines Bv (by stop				
			sign)				
09/30/10	Greater Pines	14	Side of 1300 Sandy Pine Ln on			1/4" Lift	
00/20/40		45	Greater Pines By			4 (2011)	
09/30/10	Greater Pines	15	Corner of Sandy Pine Ln and			1/2" Lift	
			Greater Pines Bv (by 13000				
			Sandy Pine)				
09/30/10	Greater Pines	16	14343 Greater Pines Bv (by			1/4" Lift- depressions	
00/20/10	Creater Biner	17	water meter)			1/2 11 125	
09/30/10	Greater Pines	17	14343 Greater Pines Bv (by			1/2 " Lift	
00/20/10	Creater Diana	10.040	electric box) Corner of Slash Pine Ct and			1/2100 bash and after	
09/30/10	Greater Pines	18 & 19				1/2 Lift both ends of ramp	
			Greater Pines Bv (by light				
L			pole)				

6. Actions - Projects Completed to Date



- Lake County performed sidewalk repairs, grind/ saw cut trip hazards, sidewalk reconstruction, and other miscellaneous improvements along public rights-ofway and new sidewalks:
- FY 2011: \$502,480.33
- FY 2012: \$451,865.35

6. Actions - Implementation



- Lake County will implement the Transition Plan as follows:
- FY 2013-2017 \$2,500,000
- FY 2018 2022 \$2,500,000
- Continue depending on available funding

6. Actions - Curb Ramp Request Form



			CUR	B RAM	IP											
			Prog	rai	m Acce	ess Re	quest	t Fo	rm							
LAKE COU		Y					•									
TLOKID	<u></u>		ISSUE								1	OCAT				
No Curb Ra	able Warnings		Crackee	d Surface												
Running Slope (stee	ep) 🗆					Slippery							⊢			
	Cross Slope				Obstructions				I		_	CROSS STREET				
Other (spec	fy)							_	-				SS 5			
									r	_			З,	_		
													L			- 📖
		F	REQUEST		D. d. d.	0	_									
New Curb Ra Other (spec			Repair	Ш	Pedestri	an Signal			PRIMARY STREET							
Other (spec	(V												- F	_		- -
									l				- F			
														_		
		CONTAC						_					- F			
		SONTAG						_					- 1			
Name:											I		_ 1			
Tel:								Mark with an "X" Location of Curb Ramp								
Address:								Pri	mary s	St.						
E-mail:																
Date:								С	ross	St.						
					OFFICIA	L USE C										
			1		OFFICIA	L USE C										
ADA RW Coordinat	or: Ros	s Pluta					ADA Tra	nsitio	n Plai			DAT	E			1
Т	el: (35)	2) 483- 9	0041					1	Year		Submit	ted			~	
F	ix:						A	ssess	ment		Respon	se				
Addre	s: 437	Ardice A	ve., Eustis, FL	. 32	726						Appeal					5
Address: 437 Ardice Ave., Eustis, FL 32726 E-mail: BPluta@lakecountvfl.gov								Agreem	ent							
6 -111		atore i on out	Zar ityzt tr <u>tato y</u>							- 1'	sgreen	- TR				

6. Actions – Sidewalk Request Form



		A			SID	EWAL	۲						
LAK	CE COU		Prog	rai	m Acce	ess Red	quest	t Form					
Litte	FLORID												
			ISSUE						LOC	ATION			
No	Sidewalk		Passing Space		Bus	Stop Pad							
Surfa	ace Slope	Char	ge in Level (step)			Crosswalk			- 1	- I			
	Narrow	No	Pedestrian Signa		Obstructions								
					(Pole, Bo	x, Grass,			iii I	4	Ш –		
Other	r (specify)								I STREET	N	STREET		
										'			
			REQUEST						CROSS		CROSS		
New	Sidewalk		Repair		Pedestri	an Signal			2 I		ы К		
Other	r (specify)					Ť			0- <u></u>				
	• •												
-									PRIMAR	Y STREET			
				_									
		CON	TACT INFORMAT										
		CON							•	•	• ⊢		
Name:								Mark with an "X" Location of Issue on the Sidewalk					
Tel:													
Address:								Primary St.					
E-mail:								Cross St. 1					
Date:								Cross St. 2					
					OFFICIA	L USE O	NLY						
									D	A TE			
ADA RWCoo	rdinator:	Ross Pluta	I				ADA Tra	nsition Plai	D	ATE			
	Tel:	(352) 48	3 - 9041					1 Year 🗆	Submitted				
	Fax:						A						
	Address:	437 Ardi	ce Ave., Eustis, Fl	L					Appeal				
	E-mail:	<u>BPluta@la</u>	kecountyfl.gov	_					Agreement				

7. Contact Information



Ross Pluta Project Manager/ ADA RW Coordinator Lake County Public Works 437 Ardice Ave. Eustis, FL 32726 T. (352) 483-9041/Fax. (352) 483-9015 E-mail: <u>Rpluta@lakecountyfl.gov</u>

 Eric Contreras, Assoc. AIA, CGC ADAAG Consulting Services, LLC (ACS) 1385 Coral Way Ph 401, Miami, FL, 33145
 T. (305) 285-7373 Ext. 326/ Fax. (305) 285-2363
 E-mail: econtreras@adaag-consulting.com

8. Questions and Answers



Ross Pluta
Project Manager/ADA RW Coordinator
Lake County Public Works
437 Ardice Ave.
Eustis, FL 32726
T. (352) 483-9041/Fax. (352) 483-9015
E-mail: <u>RPluta@lakecountyfl.gov</u>



LAKE COUNTY FLORIDA

Thank you.