

Section Profile

Project
 23-00280_Lake County_Media 011

No.	PSR	Upstream MH	Downstream MH	Date	Material	Total Length	Length Surveyed
1	CB1 CB2	CB1	CB2	3/31/2025	RCP	99.40	99.40
2	CB2 CB3	CB2	CB3	3/31/2025	RCP	249.90	249.90
3	CB2 CB13	CB2	CB13	3/31/2025	RCP	153.20	153.20
4	CB5 CB6	CB5	CB6	4/1/2025	RCP	24.60	24.60
5	CB3 CB4	CB3	CB4	4/1/2025	RCP	73.40	73.40
6	CB4 CB5	CB4	CB5	4/1/2025	RCP	324.20	324.20
7	CB11 CBE#2	CB11	CBE#2	4/3/2025	RCP	322.70	322.70
8	CB8 CB9	CB8	CB9	4/3/2025	RCP	48.30	48.30
10	CB9 CB10	CB9	CB10	4/3/2025	RCP	324.40	324.40
11	CB7 CBE#1	CB7	CBE#1	4/3/2025	RCP	69.10	69.10
12	CB6 CB7	CB6	CB7	4/3/2025	RCP	59.30	59.30
13	CB10 CB11	CB10	CB11	4/3/2025	RCP	26.20	26.20
15	CBE#5 CB#12	CBE#5	CB#12	4/7/2025	RCP	116.40	116.40

18 Circular = 1891.10 Total Length (13 Inspections, 1891.10 Length Surveyed)

No.	PSR	Upstream MH	Downstream MH	Date	Material	Total Length	Length Surveyed
9	CBE#3A CBE#3	CBE#3A	CBE#3	4/3/2025	RCP	76.00	76.00
14	CBE#4A CBE#4	CBE#4A	CBE#4	4/4/2025	RCP	84.40	84.40

24 Circular = 160.40 Total Length (2 Inspections, 160.40 Length Surveyed)


2051.50 Total Length (15 Inspections, 2051.50 Length Surveyed)

Inspection report

Date: 3/31/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB1 CB2
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 99.4 '	Length Surveyed: 99.4 '

City: Minneola	Drainage Area:	Upstream MH: CB1
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Parking lot	Flow Control: Not Controlled	Downstream MH: CB2
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:751	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	ACB	Catch Basin / CB2	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	6.0	MMS	Mortar Missing Small at 10 o'clock	00:02:43		S2		
	99.4	ACB	Catch Basin / CB1	00:13:14				
QSR 2100	QMR 0000	QOR 2100	SPR 2.0	MPR 0.0	OPR 2.0	SPRI 2.0	MPRI 0.0	OPRI 2.0

Inspection report

Date: 3/31/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB2 CB3
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 249.9'	Length Surveyed: 249.9'

City: Minneola	Drainage Area:	Upstream MH: CB2
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Parking lot	Flow Control: Not Controlled	Downstream MH: CB3
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:

1:1887	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	ACB	Catch Basin / CB2	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	249.9	ACB	Catch Basin / CB3	00:32:25				
	QSR 0000	QMR 0000	QOR 0000	SPR 0.0	MPR 0.0	OPR 0.0	SPRI 0.0	MPRI 0.0

Inspection report

Date: 3/31/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB2 CB13
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 153.2'	Length Surveyed: 153.2'

City: Minneola	Drainage Area:	Upstream MH: CB2
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: Not Controlled	Downstream MH: CB13
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:1157	Distance	Code	Observation	Counter	Photo	Grade
<div> <div> <div>CB13</div> <div> <div></div> <div>0.0</div> <div>ACB</div> <div>Catch Basin / CB13</div> <div>00:00:00</div> </div> </div> <div> <div>0.0</div> <div>MWL</div> <div>Water Level, 5% of the vertical dimension</div> </div> </div>						
<div> <div> <div>153.2</div> <div>ACB</div> <div>Catch Basin / CB2</div> <div>00:17:37</div> </div> <div>CB2</div> </div>						
QSR	QMR	QOR	SPR	MPR	OPR	SPRI
0000	0000	0000	0.0	0.0	0.0	0.0
						MPRI
						OPRI
						0.0
						0.0

Inspection report

Date: 4/1/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB5 CB6
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 24.6 '	Length Surveyed: 24.6 '

City: Minneola	Drainage Area:	Upstream MH: CB5
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Sidewalk	Flow Control: Not Controlled	Downstream MH: CB6
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:

1:186	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	ACB	Catch Basin / CB5	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	24.6	ACB	Catch Basin / CB6	00:07:58				
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
0000	0000	0000	0.0	0.0	0.0	0.0	0.0	0.0

Inspection report

Date: 4/1/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB3 CB4
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 73.4 '	Length Surveyed: 73.4 '

City: Minneola	Drainage Area:	Upstream MH: CB3
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Sidewalk	Flow Control: Not Controlled	Downstream MH: CB4
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:554	Distance	Code	Observation	Counter	Photo	Grade
	0.0	ACB	Catch Basin / CB3	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension			
	73.4	ACB	Catch Basin / CB4	00:09:08		
QSR 0000	QMR 0000	QOR 0000	SPR 0.0	MPR 0.0	OPR 0.0	SPRI 0.0
						MPRI 0.0
						OPRI 0.0

Inspection report

Date: 4/1/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB4 CB5
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 324.2 '	Length Surveyed: 324.2 '

City: Minneola	Drainage Area:	Upstream MH: CB4
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: Not Controlled	Downstream MH: CB5
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use:	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:

1:2447	Distance	Code	Observation	Counter	Photo	Grade
						
	0.0	AMH	Manhole / CB4	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension			
	7.6	CC	Crack Circumferential from 2 o'clock to 5 o'clock	00:04:13		S1
	31.8	MMS	Mortar Missing Small at 2 o'clock	00:06:43		S2
	324.2	ACB	Catch Basin / CB5	00:34:30		
QSR 2111	QMR 0000	QOR 2111	SPR 3.0	MPR 0.0	OPR 3.0	SPRI 1.5
						MPRI 0.0
						OPRI 1.5

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB11 CBE#2
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 322.7'	Length Surveyed: 322.7'

City: Minneola	Drainage Area:	Upstream MH: CB11
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: De-Watered using Jetter	Downstream MH: CBE#2
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:2436	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	AMH	Manhole / CB11	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	248.1	MMS	Mortar Missing Small at 5 o'clock	00:26:56	CB11 CBE#2_52 d6652c-c3	S2		
	319.3	CC	Crack Circumferential from 12 o'clock to 12 o'clock	00:34:48		S1		
	322.7	AEP	End of Pipe / CBE#2	00:35:39				
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
2111	0000	2111	3.0	0.0	3.0	1.5	0.0	1.5

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB8 CB9
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 48.3 '	Length Surveyed: 48.3 '

City: Minneola	Drainage Area:	Upstream MH: CB8
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Sidewalk	Flow Control: Not Controlled	Downstream MH: CB9
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:365	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	AMH	Manhole / CB9	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	48.3	ACB	Catch Basin / CB8	00:07:54				
	QSR 0000	QMR 0000	QOR 0000	SPR 0.0	MPR 0.0	OPR 0.0	SPRI 0.0	MPRI 0.0

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CBE#3A CBE#3
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 76.0'	Length Surveyed: 76.0'

City: Minneola	Drainage Area:	Upstream MH: CBE#3A
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: De-Watered using Jetter	Downstream MH: CBE#3
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 24"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:574	Distance	Code	Observation	Counter	Photo	Grade
CBE#3						
	0.0	ACB	Catch Basin / CBE#3	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension			
	40.0	S01 JAM	Joint Angular Medium, Start	00:04:24		
	56.3	F01 JAM	Joint Angular Medium, Finish	00:05:48		S1
	76.0	ACB	Catch Basin / CBE#3A	00:08:13		
CBE#3A						
QSR	QMR	QOR	SPR	MPR	OPR	SPRI
1300	0000	1300	3.0	0.0	3.0	1.0

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB9 CB10
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 324.4'	Length Surveyed: 324.4'

City: Minneola	Drainage Area:	Upstream MH: CB9
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: Not Controlled	Downstream MH: CB10
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:2449		Distance	Code	Observation	Counter	Photo	Grade	
	0.0	ACB	Catch Basin / CB9		00:00:00			
	0.0	MWL	Water Level, 5% of the vertical dimension					
	0.3	CC	Crack Circumferential from 11 o'clock to 1 o'clock	00:01:23		S1		
	324.4	ACB	Catch Basin / CB10		00:38:01			
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
1100	0000	1100	1.0	0.0	1.0	1.0	0.0	1.0

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB6 CB7
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 59.3 '	Length Surveyed: 59.3 '

City: Minneola	Drainage Area:	Upstream MH: CB6
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: De-Watered using Jetter	Downstream MH: CB7
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:448	Distance	Code	Observation	Counter	Photo	Grade		
	0.0	ACB	Catch Basin / CB7	00:00:00				
	0.0	MWL	Water Level, 5% of the vertical dimension					
	24.2	CC	Crack Circumferential from 4 o'clock to 5 o'clock	00:03:49		S1		
	56.4	JAM	Joint Angular Medium	00:07:19	CB6 CB7_0e63 21c1-814d	S1		
	59.3	ACB	Catch Basin / CB6	00:09:21				
QSR	QMR	QOR	SPR	MPR	OPR	SPRI	MPRI	OPRI
1200	0000	1200	2.0	0.0	2.0	1.0	0.0	1.0

Inspection report

Date: 4/3/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CB10 CB11
Year laid:	Pre-cleaning: Jetting	Direction: Downstream	Pipe Joint Length:	Total Length: 26.2 '	Length Surveyed: 26.2 '

City: Minneola	Drainage Area:	Upstream MH: CB10
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: Not Controlled	Downstream MH: CB11
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:198	Distance	Code	Observation	Counter	Photo	Grade
						
	0.0	ACB	Catch Basin / CB10	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension			
	26.1	ACB	Catch Basin / CB11	00:06:26		
QSR 0000	QMR 0000	QOR 0000	SPR 0.0	MPR 0.0	OPR 0.0	SPRI 0.0
						MPRI 0.0
						OPRI 0.0

Inspection report

Date: 4/4/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CBE#4A CBE#4
Year laid:	Pre-cleaning: Heavy Cleaning	Direction: Upstream	Pipe Joint Length:	Total Length: 84.4 '	Length Surveyed: 84.4 '

City: Minneola	Drainage Area:	Upstream MH: CBE#4A
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Easement/Right of way	Flow Control: De-Watered using Jetter	Downstream MH: CBE#4
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 24 "	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:


1:637	Distance	Code	Observation	Counter	Photo	Grade
						
	0.0	ACB	Catch Basin / CBE#4	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension		CBE#4A CBE#4_dc e9f470-ef8	
	65.0	CC	Crack Circumferential from 6 o'clock to 7 o'clock	00:11:21		S1
	80.9	IR	Infiltration Runner at 6 o'clock	00:13:46		M4
	86.4	ACB	Catch Basin / CBE#4A	00:16:15		
QSR	QMR	QOR	SPR	MPR	OPR	SPRI
1100	4100	4111	1.0	4.0	5.0	1.0
						MPRI
						OPRI
						4.0
						2.5

Inspection report

Date: 4/7/2025	Work Order:	Weather: Dry	Surveyed By: Revertus Bratcher	Certificate Number: P0043906-092023	Pipe Segment Ref.: CBE#5 CB#12
Year laid:	Pre-cleaning: Jetting	Direction: Upstream	Pipe Joint Length:	Total Length: 116.4'	Length Surveyed: 116.4'

City: Minneola	Drainage Area:	Upstream MH: CBE#5
Street: 13930 Education Ave	Media Label:	Up Rim to Invert:
Location Code: Other	Flow Control: De-Watered using Jetter	Downstream MH: CB#12
Location Details:	Sheet Number:	Down Rim to Invert:
Pipe shape: Circular	Sewer Use: Stormwater	Total gallons used: 0.0
Pipe size: 18"	Sewer Category: SEC	Joints passed: 0
Pipe material: Reinforced Concrete Pipe	Purpose: Routine Assessment	Joints failed: 0
Lining Method:	Owner: Lake County	

Additional Info:

1:879	Distance	Code	Observation	Counter	Photo	Grade
						
	0.0	AMH	Manhole / CB#12	00:00:00		
	0.0	MWL	Water Level, 5% of the vertical dimension			
	95.6	CM	Crack Multiple from 7 o'clock to 11 o'clock	00:11:39		S3
	116.4	ACB	Catch Basin / CBE#5	00:14:11		
QSR	QMR	QOR	SPR	MPR	OPR	SPRI
3100	0000	3100	3.0	0.0	3.0	3.0