

**PIPE REPLACEMENT REQUEST**

Road Name: CR 44 Road #: 6068 Segment #: 35

Address: Under 44 just East of Sunrise Ln

Section: 7 Township: 19 Range: 27

Description of Problem: Culvert is rotten.

Description of Existing Pipe: 24" corrugated metal pipe

Pipe required: 95 ft of 24" CMP

Cover: 4 ft 10 in

Bottom of culvert to ground level: 6 ft 10 in

Inlet/Outlet Ends: concrete headwalls

Roadway to be cut out and replaced: 48 ft x 10 ft

Sod Required: any disturbed areas

# Request Details Report

Request Number  
MA3-8117-R

Associated Work Order

Observed Date/Time  
2/1/11 1:30:P

---

## ***Citizen Information***

Name	Phone	Ext.
Address	Alternate Phone	
	Email Address	

## Organization

Requestor Lake County Public Works  
Contact Dean, Randy

---

## ***Issue and Location***

Activity

Issue

Drainage

Map Page  
214

Section  
7

Address Number

Route CR 44 (6068)

Intersect Route Sunrise Ln (5574)

## Details

Supervisor noticed a problem with the culvert.

## Notes

## History


2/1/2011	Contract pipe TV requested.	Lee, Steven
2/2/2011	Contract pipe replacement requested.	Lee, Steven

Resolution \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Request Response Date 02/01/2011

Date \_\_\_\_\_  
Time Arrived \_\_\_\_\_  
Time Departed \_\_\_\_\_





**MAINTENANCE AREA 3 ASSET**

*Lake County Road Operations*  
*May 2008 Edition*

- County Segments
- G0500A-H Guardrails
- Township - Range
- Sign
- Sect
- Street