## PIPE REPLACEMENT REQUEST

Road Name:	Palmetto Rd	Road #: 9787M	Segment #: <u>01</u>					
Address:	24048							
Section: <u>30</u>	Township: 15	Range: <u>28</u>						
Description of Problem: <u>Culvert is collapsing.</u>								
Description of Existing Pipe: <u>15" corrugated metal pipe</u>								
Pipe required: 70 ft of 15" CMP								
Cover: <u>12"</u>								
Bottom of culvert to ground level: _27"								
Inlet/Outlet Ends: <u>concrete mitered ends</u>								
Roadway to be cut out and replaced: 8 x 12 ft asphalt driveway apron								
Sod Required:	720 sq ft							

## Request Details Report

MA3-8113-				Observed Date/Time 1/31/11 12:06:P	
Citizen Info Name Address		Mr. Smith	Phone Alternate Phor Email Addres	1е	Ext.
Organization Requestor Contact					
Issue and I Activity	ocation.		Issue Map Page 25	Drainage Section 30	
Address N	umber				
Route Palm	etto Rd (9787	7M)			
<b>Details</b> Citizen called number.	the main Public	Works office to rep	oort a badly rusted cul	lvert. He did not l	eave his phor
Notes					
History					
1/31/2011	Request has be	een printed and give	en to the Supervisor.		Wall, Treeva
2/2/2011	Contract pipe r	replaceme <mark>nt reques</mark>	ted.		Lee, Steven
Res	solution				
Request Resp	onse Date 01/3	31/2011			
	ne Arrived				

