

**PIPE REPLACEMENT REQUEST**

Road Name: Pine St Road #: 7366 Segment #: 02

Address: North side of 450A

Section: 24 Township: 18 Range: 26

Description of Problem: Pipe is rotten and deteriorating.

Description of Existing Pipe: 30" Corrugated Metal Pipe

Pipe required: Existing 55 ft, requesting 72 ft if possible, with headwalls.

Cover: 6 ft

Bottom of culvert to ground level: 8 ft 4 in

Inlet/Outlet Ends: Nothing currently, requesting headwalls.

Roadway to be cut out and replaced: 15 ft by 20 ft

Sod Required: Replace disturbed areas.

# Request Details Report

**Request Number** MA3-9568-R      **Associated Work Order** OSC-2186-WO      **Observed Date/Time** 5/23/12 10:41:A

---

## *Citizen Information*

**Name** \_\_\_\_\_ **Phone** \_\_\_\_\_ **Ext.** \_\_\_\_\_  
**Address** \_\_\_\_\_ **Alternate Phone** \_\_\_\_\_  
\_\_\_\_\_ **Email Address** \_\_\_\_\_

## Organization

**Requestor** Lake County Public Works  
**Contact** Dean, Randy

---

**Issue and Location** \_\_\_\_\_ **Issue** \_\_\_\_\_ **Drainage** \_\_\_\_\_  
**Activity** \_\_\_\_\_ **Map Page** \_\_\_\_\_ **Section** \_\_\_\_\_

OSC Pipe Inspection

## **Address Number**

**Route** CR 450A (7270)

**Intersect Route** Pine St (7366)

## **Details**

Supervisor noticed a culvert needing repair.

## **Notes**

For work done by Maintenance Area, see MA3-15424-WO.

## **History**

5/23/2012	Request has been printed and given to the Supervisor.	Wall, Treeva
5/25/2012	Contract pipe TV requested.	Lee, Steven
5/30/2012	Contract pipe replacement requested.	Lee, Steven

**Resolution** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Request Response Date** 05/23/2012 \_\_\_\_\_  
**Date** \_\_\_\_\_  
**Time Arrived** \_\_\_\_\_  
**Time Departed** \_\_\_\_\_