

ECI Estep Construction, Inc.

Invoice

Fax: 407-884-6904 689 Binion Road Apopka, FL 32703

JAN 2 0 2015

Date	Invoice #
1/19/2015	583

LAKE COUNTY

Bill To

Lake County PW Road Operations 12901 County Landfill Rd Tavares, FL 32778

CC/Ship To:

Contract #13-0607 mod 1 PO #20150035 Clean & Video pipe on Mills St by 899 So. Central Ave Umatilla

P.O./Contract#	Terms	Due Date	Ship Date	Ship Via	Project
	Due on receipt	1/19/2015			

Item		Description		Quantity	/	Unit Pr	Amount
1 1	Mills St by 8 Pipe Cleaning 18" - I Video Recording 18"	399 South Central Ave Light	PO#: Acct#:	222 222 OK T CSTEP CONST 20150035	LF LF CF LF	1.50 1.00 2/15 ON INC	333.00 222.00
Thank you for yo	pur business.			т	otal		\$555.00

Balance Due



Date:	1-13-2015	
Estep Co	nstruction, Inc.	
689 S. Bi	nion Road, Apopka, FL 32703	

Subject:

Project Order Form

Contract No. 13-0607, Storm Water Pipe/Water Quality Unit

Cleaning, Video Recording and Related Services

Purchase Order No. 20150035

Dear Estep Construction:

Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below.

Any questions or descrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778.

Pursuant to the Contract, all work shall begin within fourteen (14) calendar days from receipt of this notice. Please make sure to contact our office regarding the scheduling of this work.

PIPE LOCATION: Road Name: Mills Street (3-7264-01) Address: On Mills Street by 899 South Central Avenue Section: Township: 18 Range: PIPE SPECIFICATIONS: Diameter: See Below Length: 222 Number of Manholes/Inlets: Percentage of Blockage: 10% or les 11% - 30% above 30% **WORK DESCRIPTION:** Pipe size 18" CMP at inlet, 21" x 30" elliptical at outlet. Please clean and video, possible pipe failure. Two depressions visible approximately 67' from inlet and 100' from inlet. Work Completed and OK to PAY: Invoice # Robert Baker 1/19/2015 Inspected by

iPEK SPEZIAL-TV GesmbH Dürenbodenstr. 7 / A-6992 Hirschegg



Project Information

- 1			
	PROJECT NAME:	CREATED:	CATALOG NAME:
	lake county fl 01-16-15	2015.01.16	NASSCO PACP-4
	CUSTOMER:	PROJECT LEADER:	CONTRACTOR:
	Lake County	Robert Hersey	Estep Construction Inc

Customer:	Lake County
Responsible:	
Department:	
Post-Office Box:	
Street:	
Location:	
Telephone:	
Telefax:	
Mobile Phone:	
E-Mail:	
Project Leader:	Robert Hersey
Responsible:	
Department:	
Post-Office Box:	
Street:	
Location:	
Telephone:	
Telefax:	
Mobile Phone:	
E-Mail:	
Contractor:	Estep Construction Inc
Responsible:	
Department:	
Post-Office Box:	
Street:	
Location:	
Telephone:	
Telefax:	
Mobile Phone:	
E-Mail:	





Table Of Contents

PROJECT NAME:	CREATED:	CATALOG NAME:
lake county fl 01-16-15	2015.01.16	NASSCO PACP-4
CUSTOMER:	PROJECT LEADER:	CONTRACTOR:
Lake County	Robert Hersey	Estep Construction Inc

Project Information	Page 1
Table Of Contents	Page 2
Section List	Page 3
Defect Grade Description	Page 4
Section: 1a - 1b	Page 5



Section List

PROJECT NAME:	CREATED:	CATALOG NAME:
lake county fl 01-16-15	2015.01.16	NASSCO PACP-4
CUSTOMER:	PROJECT LEADER:	CONTRACTOR:
Lake County	Robert Hersey	Estep Construction Inc

No.	Section	City	Street	Length	Length Total	Date
1	1a - 1b		mills st	219.60 ft	219.60 ft	2015.01.16
				040.00.6	240 00 #	



Defect Grade Description

PROJECT NAME:	CREATED:	CATALOG NAME:	
lake county fl 01-16-15	2015.01.16	NASSCO PACP-4	
CUSTOMER:	PROJECT LEADER:	CONTRACTOR:	
Lake County	Robert Hersey	Estep Construction Inc	

1	Excellent Condition Minor Defects - Failure unlikely in the foreseeable future.
2	Good Condition Defects that have not begun to deteriorate - Pipe unlikely to fail for at least 20 years.
3	Fair Condition Moderate defects that will continue to deteriorate - Pipe may fail in 10-20 years.
4	Poor Condition Severe defects that will become grade 5 defects within the foreseeable future - Pipe will probably fail in 5-10 years.
5	Immediate Attention Defects require immediate attention - Pipe has failed or will likely fail within the next 5 years or sooner.



Section Protocol

SECTION NAME:	SECTION NUMBER:	CATALOG NAME:
1a - 1b	1	NASSCO PACP-4
CUSTOMER:	PROJECT LEADER:	CONTRACTOR:
Lake County	Robert Hersey	Estep Construction Inc

UPSTREAM MANHOLE NUMBER:	DOWNSTREAM MANHOLE NUMBER:	DOWNSTREAM MANHOLE NUMBER:		
1a	1b	1b		
MUNICIPAL:	START NODE STREET NAME:	START NODE STREET NAME:		
	mills st	mills st		
LOCATION CODE:	DIRECTION OF SURVEY:	CALCULATED LENGTH:		
	Upstream	219.60 ft		
INSPECTION DATE:	PURPOSE OF SURVEY:	PURPOSE OF SURVEY:		
2015.01.16				
WEATHER:	SEWER MATERIAL:	EWER MATERIAL:		
	Reinforced concrete pipe	Reinforced concrete pipe		
LINING METHOD: SEWER DIAMETER C		ER DIAMETER OR HEIGHT:		
	18			
PRE-CLEANED:	SEWER SHAPE:	SEWER SHAPE:		
Jetting	Oval or Elliptical	Oval or Elliptical		
COMMON REMARKS:				

