

OLD YEAR

Estep Construction, Inc.

Fax: 407-884-6904
689 Binion Road
Apopka, FL 32703

RECEIVED

SEP 23 2015

Invoice

Date	Invoice #
9/23/2015	667

LAKE COUNTY
ROAD OPERATIONS

Bill To Lake County PW Road Operations 12901 County Landfill Rd Tavares, FL 32778	CC/Ship To: Contract #13-0607 Po #20150035 Clean and Video 18" Pipe at 12709 Lake Dora Cir
--	---

P.O./Contract #	Terms	Due Date	Ship Date	Ship Via	Project
20150035	Due on receipt	9/23/2015	9/23/2015		14-16/BO

Item	Description	Quantity		Unit Pr...	Amount
1	12709 Lake Dora Cir Pipe Cleaning - 18" - Heavy	180		LF 4.50	810.00
1	Video Recording - 18"	180		LF 1.00	180.00

SK 10/6/15

OK TO PAY - FY 14/15

PO#: 2015 0035
Acct#: 1120.5053200. 830460
Goods Recd: 9 / 22 / 2015

Thank you for your business.

Total

\$990.00

BP
10/2/15
9/1
10/2/15

Balance Due \$990.00

MB 10/7/15

KL 092315



LAKE COUNTY FLORIDA

Date: 9-21-15

Estep Construction, Inc.
689 S. Binion Road, Apopka, FL 32703

Subject: Project Order Form
Contract No. 13-0607, Storm Water Pipe/Water Quality Unit
Cleaning, Video Recording and Related Services
Purchase Order No. 20150035

Dear Estep Construction:
Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below.

Any questions or discrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778.

Pursuant to the Contract, all work shall begin within fourteen (14) calendar days from receipt of this notice. Please make sure to contact our office regarding the scheduling of this work.

PIPE LOCATION: Road Number: 3844 Segment Number: 1-3844-03

Road Name: Lake Dora Circle Address: 12709

Section: 31 Township: 19 Range: 26 Tavares

PIPE SPECIFICATIONS:

Diameter: 18" inches Length: 180' feet Number of Manholes/Inlets: _____

Percentage of Blockage: 10% or less 11% - 30% above 30%

WORK DESCRIPTION:

Pipe may have hole due to sink hole under driveway at address

Work Completed and OK to PAY:	<u>9/22/2015</u>	Invoice #	<u>667</u>
	<u>B. Press</u>		<u>9/22/2015</u>
	Inspected by		Date

Section List

PROJECT NAME: 12709 lake dora cr	CREATED: 2015.09.22	CATALOG NAME: NASSCO PACP-4
CUSTOMER: Lake County	PROJECT LEADER: Robert Hersey	CONTRACTOR: Estep Construction Inc

No.	Section	City	Street	Length	Length Total	Date
1	1 - 2		12709 lake dora cr	0.20 ft	0.20 ft	2015.09.22
2	1 - 2 (2)		12709 lake dora cr	0.00 ft	0.20 ft	2015.09.22
3	2a - 2b		12709 lake dora cr	0.00 ft	0.20 ft	2015.09.22
				0.20 ft	0.20 ft	

Section Protocol

SECTION NAME: 1 - 2	SECTION NUMBER: 1	CATALOG NAME: NASSCO PACP-4
CUSTOMER: Lake County	PROJECT LEADER: Robert Hersey	CONTRACTOR: Estep Construction Inc


UPSTREAM MANHOLE NUMBER: 1	DOWNSTREAM MANHOLE NUMBER: 2
MUNICIPAL:	START NODE STREET NAME: 12709 lake dora cr
LOCATION CODE:	DIRECTION OF SURVEY: Downstream
	CALCULATED LENGTH: 0.20 ft
INSPECTION DATE: 2015.09.22	PURPOSE OF SURVEY:
WEATHER:	SEWER MATERIAL: Corrugated metal pipe
LINING METHOD:	SEWER DIAMETER OR HEIGHT: 18
PRE-CLEANED:	SEWER SHAPE: Circular
COMMON REMARKS:	

1 : 10	POSITION	DG	CODE	OBSERVATION	VIDEO POS	PHOTO
			AEP	End of Pipe, start of video	00:00:01	
			HSV	Hole Soil Visible, at 6 o'clock, bottom of pipe gone, reversal	00:00:02	
			HSV	Hole Soil Visible, at 6 o'clock, bottom of pipe gone, reversal	00:01:57	

Section Protocol

SECTION NAME: 1 - 2 (2)	SECTION NUMBER: 2	CATALOG NAME: NASSCO PACP-4
CUSTOMER: Lake County	PROJECT LEADER: Robert Hersey	CONTRACTOR: Estep Construction Inc


UPSTREAM MANHOLE NUMBER: 1	DOWNSTREAM MANHOLE NUMBER: 2
MUNICIPAL:	START NODE STREET NAME: 12709 lake dora cr
LOCATION CODE:	DIRECTION OF SURVEY: Upstream
INSPECTION DATE: 2015.09.22	PURPOSE OF SURVEY:
WEATHER:	SEWER MATERIAL: Corrugated metal pipe
LINING METHOD:	SEWER DIAMETER OR HEIGHT: 18
PRE-CLEANED:	SEWER SHAPE: Circular
COMMON REMARKS:	
CALCULATED LENGTH: 0.00 ft	

1 : 10	POSITION	DG	CODE	OBSERVATION	VIDEO POS	PHOTO
			AJB	Junction Box, reversal	00:00:01	
			MGO	General Observation, light from surface	00:00:35	
			AEP	End of Pipe, end of video	00:00:57	

Section Protocol

SECTION NAME: 2a - 2b	SECTION NUMBER: 3	CATALOG NAME: NASSCO PACP-4
CUSTOMER: Lake County	PROJECT LEADER: Robert Hersey	CONTRACTOR: Estep Construction Inc

UPSTREAM MANHOLE NUMBER: 2a	DOWNSTREAM MANHOLE NUMBER: 2b
MUNICIPAL:	START NODE STREET NAME: 12709 lake dora cr
LOCATION CODE:	DIRECTION OF SURVEY: Upstream
INSPECTION DATE: 2015.09.22	PURPOSE OF SURVEY:
WEATHER:	SEWER MATERIAL: Corrugated metal pipe
LINING METHOD:	SEWER DIAMETER OR HEIGHT: 18
PRE-CLEANED:	SEWER SHAPE: Circular
COMMON REMARKS: pipe going to RR tracks	

1 : 10	POSITION	DG	CODE	OBSERVATION	VIDEO POS	PHOTO
			AJB	Junction Box	00:00:00	
			OBZ	Obstacles Other, 5 % of cross sectional area, at 5 o'clock	00:00:31	