Estep Construction, Inc.

820 S Duncan Drive Tavares, FL 32778

RECEIVED

FEB - 1 2017

LAKE COUNTY ROAD OPERATIONS

Invoice

| Date | Invoice # |
|----------|-----------|
| 2/1/2017 | 869 |

Bill To

Lake County PW 12901 County Landfill Rd PO Box 7800 Tavares, FL 32778 CC/Ship To:

Contract #13-0607 mod 4 PO #20170178 Clean & Video Pipes at 19215 Parl Place Blvd Eustis

| P.O./Contract # | Terms | Due Date | Ship Date | Ship Via | Project |
|-----------------|----------------|----------|-----------|----------|---------|
| 20170178 | Due on receipt | 2/1/2017 | 2/1/2017 | : | 16-17/E |

| | 170170 | Bue on receipt | 2/1/2017 | 2/1/201/ | | | 10 1771 |
|-------------------|--|----------------|--|----------|---------------|--|--------------------|
| Item | | Description | and the second s | Qua | ntity | Unit Pr | Amount |
| 1 1 | 19215 Park Pl Pipe Cleaning - 36" Video Recording | ace Blvd | | PO#: | LF LF OK TO I | 4.00 1.00 1.00 2/9/20= 2/9/20= 2/9/24 | 2,044.00 511.00 |
| Thank you for you | ır business. | | RB | 2-8-17 | Total | | \$2,555.00 |

Balance Due

\$2,555.00



| Date:1-18-2017 | | | | |
|--|--|--|--|--|
| Estep Construction, Inc. | | | | |
| 689 S. Binion Road, Apopka, FL 32703 | | | | |
| | 507, Storm Water Pipe/Water Quality Unit ecording and Related Services | | | |
| Dear Estep Construction: Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below. Any questions or descrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778. | | | | |
| notice. Please make sure to contact our office | | | | |
| PIPE LOCATION: Road Number: | 5477 Segment Number: <u>3-5477-03</u> | | | |
| Road Name: Park Place Bv. | Address: 19215 Park Place Bv. | | | |
| Section: 8 Township: 19 | Range: 27 Closest City: Eustis | | | |
| PIPE SPECIFICATIONS: | | | | |
| Diameter: 36" inch Length: 515 LF | Number of Manholes/Inlets: two(2) | | | |
| Percentage of Blockage: 10% or les X | 11% - 30% above 30% | | | |
| WORK DESCRIPTION: Video and light clean pines at 19215 Park Place | e Bv. to 34253 Woodridge Lane that are high lighted in | | | |
| | 5 BV. to 34233 Woodinage Lane that are high lighted in | | | |
| blue on the map. | | | | |
| Work Completed and OK to PAY: | 2/8/2017 Invoice # 869 | | | |

2/8/2017

Date

Robert Baker

Inspected by



Date

Estep Construction, Inc. 689 S. Binion Road, Apopka, FL 32703

Subject:

Project Order Form

Contract No. 13-0607, Storm Water Pipe/Water Quality Unit

Cleaning, Video Recording and Related Services

Purchase Order No. 20131369

Dear Estep Construction:

Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below.

Any questions or descrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778.

Pursuant to the Contract, all work shall begin within fourteen (14) calendar days from receipt of this notice. Please make sure to contact our office regarding the scheduling of this work.

| A | PIPE LOCATION | N: | Road Segn | nent No: | 3-5477-03 | | |
|---|----------------|--------------|--------------|----------|-----------|--------------------------|--------------------|
| V | Road Name: | Park Place | Bv | | Address: | 19215 Park Place By to 3 | 34253 Woodridge Ln |
| | Section: | | 8 Township: | : 19 | 9 Range: | 27 | |
| | PIPE SPECIFICA | ATIONS: | | | | | |
| | Diameter: | 36 in | Length: | 515 ft | Number of | f Manholes/Inlets: | 2 |
| | Percentage of | Blockage: | 10% or les | :5 X | 11% - 30% | above 30% | % |
| | WORK DESCRI | IPTION: | | | | | |
| | TV only. / C | leav | | | | | |
| | | | | | | | |
| | Work Complet | ted and OK t | to PAY: | | | Invoice No |). |
| | | | Inchested by | | | | Date |



Request Details Report

| Request Number MA3-15173-R | Associated Work Or | | bserved Da /11/17 1:3 | | |
|---|--------------------|--|--------------------------|-----------|-----------|
| Citizen Information Name Address | | Phone Alternate Phor Email Address | | Ext. | |
| Organization Requestor Lake County Contact Lee, Steve | Public Works | | , R | | |
| Issue and Location | | Issue | Draina | age | |
| Activity | | Map Page | SEC 8 | TWN 19 | RNG 27 |
| Address Number | | | | | |
| Route Park Place Bv (5 | 477) | | | | |
| Intersect Route Wood Details | dridge Ln (5477B) | | | | 72 |
| Pipe needs to be TV'd | | | | | 40 |
| Notes | | | | | |
| History | | | | | |
| | | | | | |
| Request Response Date 01 | | | | | |
| Date Time Arrived | | | - | | |
| Time Arrived | | | | | |

Time Departed_

PROJECT NAME: 16-17/E CUSTOMER: Lake County PROJECT LINFOrmation CREATED: CATALOG NAME: NASSCO PACP-4 CONTRACTOR: Estep Construction Inc

| Customer: | Lake County |
|------------------|-----------------|
| Responsible: | |
| Department: | |
| Post-Office Box: | Spring Cok Br. |
| Street: | Spring cox (30) |
| Location: | |
| Telephone: | |
| Telefax: | |
| Mobile Phone: | |
| E-Mail: | |

| Project Leader: | James Rash |
|------------------|------------|
| Responsible: | |
| Department: | |
| Post-Office Box: | |
| Street: | |
| Location: | |
| Telephone: | |
| Telefax: | |
| Mobile Phone: | |
| E-Mail: | |

| Contractor: | Estep Construction Inc |
|------------------|------------------------|
| Responsible: | |
| Department: | |
| Post-Office Box: | R. |
| Street: | |
| Location: | |
| Telephone: | |
| Telefax: | |
| Mobile Phone: | |
| E-Mail: | |
| | |

| | Table Of Conte | ents |
|---------------|-----------------|------------------------|
| PROJECT NAME: | CREATED: | CATALOG NAME: |
| 16-17/E | 2017.01.24 | NASSCO PACP-4 |
| CUSTOMER: | PROJECT LEADER: | CONTRACTOR: |
| Lake County | James Rash | Estep Construction Inc |

| Project Information | Page 1 |
|--------------------------|--------|
| Table Of Contents | Page 2 |
| Section List | Page 3 |
| Defect Grade Description | Page 4 |
| Section: 34253 - 19336 | Page 5 |
| Section: 19366 - 19215 | Page 6 |

| | · | |
|---------------|-----------------|------------------------|
| | Section List | |
| PROJECT NAME: | CREATED: | CATALOG NAME: |
| 16-17/E | 2017.01.24 | NASSCO PACP-4 |
| CUSTOMER: | PROJECT LEADER: | CONTRACTOR |
| Lake County | James Rash | Estep Construction Inc |

| No. | Section | City | Street | Length | Length Total | Date |
|-----|---------------|------|----------------|-----------|--------------|------------|
| 1 | 34253 - 19336 | | Spring Oak Dr. | 182.56 ft | 182.56 ft | 2017.01.24 |
| 2 | 19366 - 19215 | | Spring Oak Dr. | 328.30 ft | 510.86 ft | 2017.01.24 |

510.86 ft 510.86 ft

| Defect Grade Description | | | |
|--------------------------|-----------------|------------------------|--|
| PROJECT NAME: | CREATED: | CATALOG NAME: | |
| 16-17/E | 2017.01.24 | NASSCO PACP-4 | |
| CUSTOMER: | PROJECT LEADER: | CONTRACTOR: | |
| Lake County | James Rash | Estep Construction Inc | |

| 1 | Excellent Condition |
|---|--|
| | Minor Defects - Failure unlikely in the foreseeable future. |
| | |
| 2 | Good Condition |
| | |
| | Defects that have not begun to deteriorate - Pipe unlikely to fail for at least 20 years. |
| | |
| 3 | Fair Condition |
| | Moderate defects that will continue to deteriorate - Pipe may fail in 10-20 years. |
| | |
| 4 | Poor Condition |
| | Severe defects that will become grade 5 defects within the foreseeable future - Pipe will probably fail in 5-10 years. |
| | |
| 5 | Immediate Attention |
| | Defects require immediate attention - Pipe has failed or will likely fail within the next 5 years or sooner. |
| | |

| Section Protocol | | | |
|------------------|-----------------|------------------------|--|
| SECTION NAME: | SECTION NUMBER: | CATALOG NAME: | |
| 34253 - 19336 | 1 | NASSCO PACP-4 | |
| CUSTOMER: | PROJECT LEADER: | CONTRACTOR: | |
| Lake County | James Rash | Estep Construction Inc | |

| UPSTREAM MANHOLE NUMBER | DOWNSTREAM MANHOLE NUMBER | DOWNSTREAM MANHOLE NUMBER | | |
|-------------------------------|---------------------------|---------------------------|--|--|
| 34253 | 19336 | 19336 | | |
| MUNICIPAL: | START NODE STREET NAME: | START NODE STREET NAME: | | |
| | Spring Oak Dr. | Spring Oak Dr. | | |
| LOCATION CODE: | DIRECTION OF SURVEY: | CALCULATED LENGTH: | | |
| | Downstream | 182.56 ft | | |
| INSPECTION DATE: | PURPOSE OF SURVEY: | PURPOSE OF SURVEY: | | |
| 2017.01.24 | | | | |
| WEATHER: | SEWER MATERIAL: | | | |
| | Corrugated metal pipe | | | |
| LINING METHOD: SEWER DIAMETER | | ETER OR HEIGHT: | | |
| | 36 | 36 | | |
| PRE-CLEANED. | SEWER SHAPE: | SEWER SHAPE | | |
| | Circular | | | |
| COMMON REMARKS: | | | | |
| | | | | |
| | | | | |



| Section Protocol | | | |
|------------------|-----------------|------------------------|--|
| SECTION NAME: | SECTION NUMBER: | CATALOG NAME: | |
| 19366 - 19215 | 2 | NASSCO PACP-4 | |
| CUSTOMER: | PROJECT LEADER: | CONTRACTOR: | |
| Lake County | James Rash | Estep Construction Inc | |

| UPSTREAM MANHOLE NUMBER: | DOWNSTREAM MANHOLE NUMBER: | DOWNSTREAM MANHOLE NUMBER | | |
|--------------------------|----------------------------|---------------------------|--|--|
| 19366 | 19215 | 19215 | | |
| MUNICIPAL: | START NODE STREET NAME: | START NODE STREET NAME: | | |
| | Spring Oak Dr. | Spring Oak Dr. | | |
| LOCATION CODE: | DIRECTION OF SURVEY: | CALCULATED LENGTH: | | |
| | Downstream | 328.30 ft | | |
| INSPECTION DATE: | PURPOSE OF SURVEY | PURPOSE OF SURVEY | | |
| 2017.01.24 | | | | |
| WEATHER: SEWER MATERIAL: | | ER MATERIAL: | | |
| | Corrugated metal pipe | Corrugated metal pipe | | |
| LINING METHOD: | SEWER DIAMETER OR HEIGHT: | SEWER DIAMETER OR HEIGHT: | | |
| | 36 | | | |
| PRE-CLEANED: | SEWER SHAPE: | SEWER SHAPE: | | |
| | Circular | | | |
| COMMON REMARKS: | | | | |
| | | | | |
| | | | | |





