

2016 ANNUAL MINING PROGRESS REPORT

LONE PINE PIT – 21 Acres

Alternate Key# 1210411, 1210429, 1013283

Org MSP Tracking# 90/12/1-2

Mining Site Plan #: 1027

1. Identification of Land Mined during the proceeding year and Lands expected to be mined during the current year.

Attached is a **2014** aerial photograph delineating the approximate area mining activity during the past year and the area expected to be mined during this operational year.

2. Discussion of the Reclamation progress for each area where Reclamation has been completed in the past year or where Reclamation is in progress and a discussion of Reclamation planned for the current year.

As a Vested mine, no Reclamation is required for the previous year's mining activity. No Reclamation is planned for the current year. Minimal grading is being done to ensure that a slope of at least 2:1 remains in areas where mining has ceased. Natural vegetation propagation is occurring.

3. Aerial photographs at a scale of 1 inch = 500 feet (photos of flight most recently available through the County Engineer's office, DOT, SCS or other agency will be accepted) showing the extent of Land disturbance and Reclamation during the last year.

Please see attached **2014** aerial photograph (scale 1" = 500') delineating the project boundaries, area mined during the preceding year, and proposed mining area for the current year.

4. A summary of results on the previous year's environmental monitoring program if required in the Operating Permit.

No Environmental Monitoring is required.

5. The Operator shall also furnish copies of all related inspection reports not previously furnished which are required by state, federal, regional or local regulatory agencies.

No other agency inspections are required or have been performed.

6. An update on major Access routes, impacted intersections closest to the Site and daily volume of Vehicles hauling mined material.

The access to the site remains to be the main entrance on South Buckhill Road. The nearest impacted intersection is that of CR 455 and South Buckhill Road. **There has been no hauling of mined material.**

7. Certification.