

PHOTO 7 - 9/29/21 - APPARENT AIR EROSION OF CEILING TREATMENT IN THE EASTERN HALLWAY



PHOTO 8 - 9/29/21 - LOCALIZED PEELING CEILING TREATMENT IN THE EASTERN HALLWAY



PHOTO 9 – 9/29/21 – LOCALIZED DAMAGE AND AIR EROSION OF CEILING TREATMENT ABOVE ROOM 15



PHOTO 10 – 9/29/21 – LOCALIZED DAMAGE AND AIR EROSION OF CEILING TREATMENT ABOVE CUBICLE 31



PHOTO 11 - 9/29/21 – PEELING CEILING TREATMENT SOUTHERN PORTION OF THE BUILDING




PHOTO 12 – 9/29/21 – PEELING CEILING TREATMENT CEILING TREATMENT ABOVE ROOM 23



PHOTO 13 – 9/29/21 – APPARENT AIR EROSION AND DELAMINATION CEILING TREATMENT ABOVE ROOMS 24 AND 25



PHOTO 14 – 9/29/21 – INTACT EXPOSED CEILING TREATMENT ROOM 4