LAKE COUNTY
FLORIDA

To: _____   **From: Public Works/Road Ops**

Fax: _____   **Pages:** _____1_____

Phone: _____   **Date:** _____9/21/2017_____

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Tuscawilla Dr. Segment No.: 1-4120-01
Nearest City:Leesburg
Address: 6720 Tuscawilla Dr. Leesburg, FL 34748
Section   31   Township: 19   Range: 25
Description of Tree: Water Oak
Location of Tree: Across the street from address 6720 Tuscawilla Dr.
Size of tree (s): 40"
Grind Stump? yes   Remove Stump? _____
If trim what class? Class 1 ☐   Class 2 ☐   Class 3 ☐
Power Lines or other hazards involved? Yes ☒   No ☐
Sod? Yes ☐   No ☒   Type of sod Needed: _____

Comments:Tree is leaning over road towards power lines.

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract.   Invoices should be sent to the address listed below.

Approved by: _____   Date: _____
              County Representative

Work Completed and OK to Pay: Yes ☐ No ☐
Inspected by: _____   Date: _____
Invoice # _____

Request Details Report

Request Number	Associated Work Order	Observed Date/Time
MA1-12200-R		9/20/17 11:45:A

Citizen Information

Name Ryan Langston **Phone** (352) 552-1528 **Ext.**

Address **Alternate Phone**

Not Provided (0000) **Email Address**

Organization

Requestor

Contact

Issue and Location

Issue Tree Removal

Activity **Map Page** **SEC** **TWN** **RNG**

TRE Removal

Address Number

Route Tuscawilla Dr (4120)

Intersect Route

Details

Mr. Langston requested to speak with a Supervisor regarding a tree that is leaning in the road that will fall at any point. He is concerned that the tree can hurt someone if it falls.

Notes

History

9/20/2017	Checked tree and tree shows signs of still being green and alive. Talked to Mr. Langston and made him aware that we are not allowed to removed live trees but because this one is leaning really low in the road we will see if it can be sent to contracts for removal.	Kent, Charlie
9/20/2017	Mr. Langston was made aware that his request would be handed to the Supervisor for further investigation.	nbautista

Resolution _____

_____

_____

Request Response Date 09/20/2017 _____

Date _____

Time Arrived _____

Time Departed _____

Tuscawilla Dr.

3812303   15

3839969

3784703
3812316   3784710   3812314   38123
3812313 3784706   3812300   3784700
3812311
3812308 3812306   3812310   3812317   3784709   3812315
3784702   3812304   3812312   3784701   3812309

29

SECRETARIAT TRL

6708
1738644   3
38636

6720

1738652   4

1

Approximate location of leaning tree.

TUSCAWILLA DR

3891364

ORB 870/828

6721

809400   2
701 ORB 870/828

ORB 870/828
2742780

2809396
ORB 870/828   1738661
6732

6

Tuscawilla Dr. (4120)

Tuscawilla Dr. (4120)

Tuscawilla Dr. (4120)

Tuscawilla Dr. (4120)

Tuscawilla Dr. (4120)