

Priority Project #2

Add Crosswalk on Fosgate Rd at west School Driveway





Findings:

✓ There are no crosswalk markings or detectable warnings at the western school driveway on Fosgate Rd (right turn exit only)

Recommendations:

 Mark crosswalk at west school driveway on Fosgate Rd and install missing detectable warnings