

### Findings:

- ✓ Several students were observed to walk home north on Gadson St
- ✓ Existing sidewalk stops just south of Hart St and is of substandard width located at the edge of the roadway

### Recommendation:

- ✓ Reconstruct Gadson St sidewalk north of Parkwood St (east side of road) to 5 ft with roadway buffer

