





Grassy Lake Rd west of Jack Pine St



ADA Grade Issue at existing crosswalk



Debris/sand at sidewalk connection

Findings:

- ✓ Crosswalk facilitates shift of sidewalk from north side to south side of roadway
- ✓ Crosswalk connects to existing utilities access driveway with significant grade (does not meet ADA)
- ✓ Sidewalk connecting to driveway is covered with sand/debris
- ✓ Crosswalk does not have any lighting

Recommendations:

- ✓ Shift midblock crosswalk further east (~200 ft) to avoid ADA/grade issue
- ✓ Add lighting so crosswalk is well lit and meets illumination standards
- ✓ Add advance yield lines (30 ft separation) & yield here to pedestrians signs

