

Recommendations:

- ✓ Update existing school zone speed limit sign on Vine St east of Moss St (eastbound) to use flashing beacons rather than sign plaque with times

