



Findings:

- ✓ Existing crosswalk is located between the student lots
- ✓ Observations were made of vehicles not yielding to pedestrians in the crosswalk
- ✓ Majority of traffic is coming from and going to the south (CR 565A)

Recommendations:

- ✓ Relocate the existing crosswalk between the student lots to north of the underclassman parking lot and connect to existing sidewalk on east side of roadway
- ✓ Install lighting and update markings
- ✓ Install the standard treatment for a midblock crosswalk

