



Water Leak



Water Leak



Water Spot from
above Roof Leak

Hose bibb not
in operation.



FACP

Hose bibb not
in operation.



Hose bibb valve in open position.




Hose bibb valve in open position.





Warm air entering to the building through kitchen




Missed electrical cover plate (kitchen hood motor).

Air Handler closet folding door top frame is loose.



Air Handler closet folding door top frame is loose.



GENERATOR FAULTS

- Overcrank
- High Engine Temperature
- Low Oil Pressure
- Overspeed
- Emergency Stop
- Low Fuel
- Low Coolant Level/Aux
- Low Coolant Temperature
- Low Cranking Voltage
- Battery Voltage (Hi/Lo)
- Battery Charger Fail
- Common Fault

SYSTEM STATUS

- EPS Supplying Load
- Not-In-Auto
- System Ready
- Generator Running
- Communication Status

System ID:

KOHLER

GENERAL FAULTS

- [Blank indicator]

LAMP TEST

ATS Fault SOURCE

N E

TEST

LOCK

UN-LOCK

CONTROL



Temporary power and water service need to be removed from the site and properly discarded.



Bay overhead doors sensors are not working.



Bay overhead doors sensors are not working.



Existing grease trap has not been removed as required per Utility Plan sheet 1.5.



Existing grease trap has not been removed as required per Utility Plan sheet



HVAC Condensate Drain not installed per drawings, refer to sheet P601, detail #4 "French Drain Detail". Condensate drain line and French Drain must be installed per detail (including but not limited to plastic valve box with cover and 3/4" stone).

