



LAKE COUNTY  
FLORIDA

To: \_\_\_\_\_ From: **Public Works/Road Ops**

Fax: \_\_\_\_\_ Pages: **1**

Phone: \_\_\_\_\_ Date: **11/4/2010**

E-Mail: \_\_\_\_\_

**TREE REMOVAL REQUEST**

Road Name: Southland Rd Segment No.: 3-4466-01

Nearest City: Mount Dora

Address: 2637

Section 25 Township: 19 Range: 26

Description of Tree: Oak

Location of Tree: Between sidewalk and road.

Size of tree (s): 38"

Grind Stump? yes Remove Stump? \_\_\_\_\_

If trim what class? Class 1  Class 2  Class 3

Power Lines or other hazards involved? Yes  No

Sod? Yes  No  Type of sod Needed: \_\_\_\_\_

Comments: Tree is marked with flagging tape.

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Approved by: \_\_\_\_\_ Date: \_\_\_\_\_  
County Representative

<b>Work Completed and OK to Pay:</b> Yes <input type="checkbox"/> No <input type="checkbox"/>
<b>Inspected by:</b> _____ <b>Date:</b> _____
<b>Invoice #</b> _____

Lake County Road Operations, 28127 County Road 561, Tavares, Florida 32778, Phone  
Number: 352-343-6439 – Fax Number: 352-742-3511

# Request Details Report

Request Number  
MA3-7938-R

Associated Work Order

Observed Date/Time  
10/29/10 10:22:A

---

## **Citizen Information**

Name Gary Phone (352) 383-2734 Ext.  
Address Not Provided (0000) Alternate Phone  
Email Address

Organization  
Requestor  
Contact

---

## **Issue and Location**

Activity

Issue

Map Page

Tree Removal  
Section

Address Number 2637

Route Southland Rd (4466)

Intersect Route

### **Details**

Citizen reports a tree between the road and the sidewalk is in bad shape, and has dropped a limb which is blocking the sidewalk.

## **Notes**

## **History**

10/29/2010	Request has been printed and given to the Supervisor.	Wall, Treeva
11/1/2010	Requesting that John Bringard have the Arborist examine the tree.	Lee, Steven
11/4/2010	Arborist reports the tree is past its life expectancy. Internal decay, lifting sidewalk, conks in crown, weak wood. Recommends removal.	Bringard, John

Resolution \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Request Response Date \_\_\_\_\_

Date \_\_\_\_\_

Time Arrived \_\_\_\_\_

Time Departed \_\_\_\_\_



HERE

LC-F-106

LAKE GERTRUDE

LAKE TEM

LAKE DORA

SPRING HARBOR BLVD

EUDORA RD

EASTLAND RD

WESTLAND

SOUTHLAND RD

PALMETTO RD

WASHINGTON RD

SHERIDAN RD

FLORENCE RD

OLD US HWY 441

MARYLIN

MAGNOLIA DR

GREENWAY DR

LUCERNE DR

PALMETTO DR

WASHINGTON DR

SHERIDAN DR

FLORENCE DR

OLD US HWY 441

GORDON LN

OLD US HWY 441

KEN CT

DAVID CT

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

INDIANA AV

