



LAKE COUNTY
FLORIDA

To: **Absolute Line Technologies** From **Public Works Road Ops**
E-mail: Phone: **(352) 343-6439**
Fax: **383-8085** Page: **1**
Phone: **383-0002** Date: **1/7/2014**
Pipe Cleaning & Video, 10-0609

WORK REQUEST

Date of Video and/or Report Due: **ASAP**

Road Name: **Royal Trails Rd**

Address: **@ Greenbrier St**

Segment Number: **3-7997-07**

Section: **18** Township: **18**

Range: **29**

Location: **Under Royal trails Rd @ Greenbrier St**

Description of work to be performed: **Cleaning - There are two pipes, one on each side of Greenbrier St. Both have a drop-box inlet with an open outlet.**

Pipe Size: **Two - 18" x 50' each**

Percentage of pipe blocked: **10% or less** **11% - 30%** **above 30%**

Pipe Length: **50' each** Number of Man holes: **2**

Clean only:

TV only:

Cleaning/TV:

Total footage for this request: **100'**

If there are questions concerning pipe size(s), length(s) or the % of blockage shall be addressed and agreed upon in writing by the County Representative prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Request Details Report

Request Number MA3-11581-R Associated Work Order MA3-19035-WO Observed Date/Time 12/27/13 1:11:P

Citizen Information

Name	Phone	Ext.
Address	Alternate Phone	
	Email Address	

Organization

Requestor Lake County Public Works
Contact Martin, Sid

Issue and Location

Activity	Issue Map Page	Drainage SEC TWN RNG
----------	-------------------	-------------------------------

Address Number

Route Royal Trails Rd (7997)

Intersect Route Greenbrier St (7697)

Details

Pipe that runs under Greenbrier - rip rap headwall falling apart, erosion, and delineators falling down. Per Jeff Johnson, take a look and see what needs to be done.

Notes

01/07/13 - Discussed at staff meeting. Pipes are under Royal Trails Rd.

History

1/7/2014 Contract pipe cleaning requested. Lee, Steven

Resolution _____

Request Response Date 12/27/2013

Date _____

Time Arrived _____

Time Departed _____


Stormwater inspector looked at the pipe ... there is fresh disturbance in the area – a bag of riprap looks like it was pulled out of the pipe.

Both headwalls are covered with dirt.

Suspect that both headwalls need to be replaced, but won't know exactly until they are unearthed.

Pipes need to be cleaned.

Erosion is the dirt that has slowly, over time, washed down and covered the headwalls.



Lake County Road Operations
May 2008 Edition

MAINTENANCE AREA 3 ASSET BO

-  County Segments
-  60500A-H Guardrails
-  Township - Range
-  Signs
-  Sections
-  Streets