



To:	From: Pub	lic Works/Road Ops
Fax:	Pages:	1
Phone:	Date:	6/21/2017
E-Mail:		
TREE REMOVAL REQUES	T	
Questions concerning tree size(s) shall be a or designee prior to the performance of the	Range: 26 es driveway side, 35" ump? Class 2 Volved? Yes Type of so with flagging to ended and agree work. Any work	Class 3 No
Approved by: County Representa	Date:	
County Nepresente	ici v C	
Work Completed and OK to	Pay: Yes	No
Inspected by:		Date:
Invoice #		

Request Details Report

Request Number MA3-15636-R			Observed Date/Time 6/19/17 7:39:A		
Citizen Information Name Address		Phone Alternate Pho Email Address		Ext.	-
Organization Requestor Lake County	Sheriff's Office				
Issue and Location Activity TRE Removal Address Number 230	0	Issue Map Page	Tree I SEC	Removal TWN	RNG
Route Southland Rd (44	466)				
Intersect Route Details A tree fell across the road. It	has been moved to th	e ROW.			
Notes					
History 6/21/2017 Contract tree	removal requested.			Lee, S	Steven
Resolution					
Request Response Date	19/2017				

Time Departed_____





Use of directions and maps is subject to our <u>Terms of Use</u>. We don't guarantee accuracy, route conditions or usability. You assume all risk of use.



Book a hotel tonight and save with some great deals! (1-877-577-5766)



MapQuest Roadside Assistance is here: (1-888-461-3625)

Wall, Treeva

From:

Lee, Steve

Sent:

Tuesday, June 20, 2017 11:09 AM

To: Subject: Wall, Treeva Dying tree


Attachments:


20170620_110720_resized.jpg; 20170620_110710_resized.jpg; 20170620_110700

_resized.jpg

40" oak tree grind stump no power lines

Sent from my Sprint Samsung Galaxy S® 6.







Wall, Treeva

From:

Lee, Steve

Sent:

Tuesday, June 20, 2017 11:06 AM

To: Subject: Wall, Treeva

Attachments:

Dying oak tree 20170620_110353_resized.jpg; 20170620_110335_resized.jpg; 20170620_110329

_resized.jpg

35" grind stump no poeer lines

Sent from my Sprint Samsung Galaxy S® 6.

