

Invoice

Date	Invoice #			
12/30/2015	6658			

Bill To					
LAKE COUNTY PUBLIC WORKS PO BOX 7800	R	EC	\mathbb{E}	IVE	
TAVARES, FL 32778	jos s	DEC	3 0	2015	
	P(LAKE	CO	UNTY	NO

Project Description	GUARDRAIL REPAIR
Contract #	
Financial Project#	G9482-A
Dates of Service/	
Date of Completion	
Location	CR 445A

Work Order No

Item No	Quantity	Description		U/M	Unit Price	Total
MISC LF MISC LF MISC EACH	12.5 37.5 2 3 1 3 1 62.5	REALIGN GUARDRAIL GUARDRAIL PANEL STEEL POSTS OFFSET BLOCKS END ANC ASSY SRT 350 REFLECTORS 6" LINEAR REFLECTIVE SYSTEM REMOVAL		LF LF EA EA EA EA LF	3.00 9.00 65.00 8.00 1,700.00 4.00 14.75 1.00	37.50 337.50 130.00 24.00 1,700.00 12.00 14.75
		CONTRACTOR'S SIGNATURE:	OK TO PAY I SOUTHEAST GU TO RISK MG Goods Recd:	MT: _/_	18114 2413	
				Balaı	nce Due	\$2,318.25

FDOT DBE CERTIFIED PALM BEACH COUNTY SWBE CERTIFIED





To:	Southeast Guardrail & Attn., Inc.	From:	Public Works Road Operations Div.	
Fax:	(561) 792-9798	Phone:	(352) 343-6439	
Phone:	(561) 792 -0040	Date:	1/5/2016	
E-Mail:	bmandellsga@aol.com	Pages:	3	
	604, Guardrail / Handrail Repair So DUOTE REQUEST	ervice Requ	<u>iest</u>	
	me: <u>CR 445A</u> Segment Number: <u>3-</u>	9482-07		
	Il Number: <u>G9482-A</u>			
Location	intersection of CR 44 and SR 40			
Nearest (City: Astor Park			
Section: 5	B Township: <u>16</u> Range: <u>27</u>			
Length o	f damage if not an end:			
Ends dan	naged? Yes 🗵 No 🗌			
If yes, h	ow many? <u>one</u>			
Commen	ts: Repair per supplied pictures	. Repair as _l	phalt base as needed	
	s should be addressed and agreed up rmance of work.	oon in writ	ing by either the Project Manager or designee pr	ior to
A nnwaya	d hy: Robert Raker date: 11-4-	2015		

County Representative

Work completed OK to Pay Date: 12-24-2015	Invoice #	6658		
Approved by: Robert Baker	Goods Received	12-24-2015		

Guardrail Work Quote Request All prices include installation

Project Name and Location

G9482-A, CR 445A

Contractor

SEA

				UNIT	TOTAL
TEN	1 DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL PRICE
	Prosting Conduct (Single Face)		LF	\$ \$	
1.	Resetting Guardrail (Single Face) Resetting Guardrail (Double Face)		LF	S . \$	
Ö	Re-alignment of existing guardrail	12.5	LF	5300 50	37.
2.001.000	New Guardrail-Including Post, Offset Blocks,	13			
•	Reflectors, Delineator Assemblies, Hardware etc.		LF	s s	
(Guardrail Panels	37.5	LF	5 900 53	37.50
3	Guardrail Posts	2	EA		130.00
7.	Encased Guardrail Post		EA	S S	
(8)	Offset Blocks	3	EA	5 8.00 S	34.0D
7.	Special End Shoes		EA	SS_	Andrew Arrange & Southern Street Street Andrew Street Stre
10.	Terminal Connector		EA	SS	
11.	Flared End Section		EA	5 5	
12.	Half Rounded End Section		EA	\$\$_	
13.	Full Rounded Buffer End Section		EA	\$\$_	
14.	Anchor Plate Assembly		EA	\$\$_	
15.	Type II End Anchorage Assembly		EA	\$\$	
16.	End Anchorage Assembly Type MELT		EA	\$\$	
17.	End Anchorage Assembly Type CRT		EA	S S	
18.	End Anchorage Assembly Type ET-2000		EA	s . s_	
19.)	End Anchorage Assembly Type SRT-350	-	F 4	s 1700, s	170000
20	(8 post system)		EA		1 100
20.	End Anchorage Assembly Type BEST		EA EA	S S S	
21. 22.	End Anchorage Assembly Type LET End Anchorage Assembly Type SKT-350		EA	S S	
23.	End Anchorage Assembly Type FLEAT-350		EA	5 5	Contract of the state of
24.	End Anchorage Assembly Type REGENT		EA	s s	
25.	Repair Existing Bridge End Assembly		EA	\$ \$	
26.	Steel Anchor Post (Bridge)		EA	S S	
27.	Concrete Anchor Post (Bridge)		EA	\$ \$	
28.	End Post with Special End Shoe Recess (Bridge)		EA	s s	and the second s
29.	Special Steel Guardrail Post for Single or double face Guardrail (where culverts or other structures preclud				
	Normal installation).		EA	\$ \$	
30.	Transition Panel from trie-beam to w-beam		EA	\$\$_	
31.	Detail J Bridge Anchorage		EA	\$ \$	
32.	ET 2000 Extruder Head		EA	\$ \$	
33.	SKT – 350 Extruder Head		EA	5 5	
34.	FLEAT 350 Extruder Head	5	EA	55_	10 00
35) 36.	Reflectors	3	EA	54, 5	12.00
36.	4" Linear Reflective System		EA	5 5	
27	(include the manufacture type and specifications)	¥	T' A	(14.75)	14.75
37)	6" Linear Reflective System	1	EA	3?	F

38. 39 40. 41. 42. 43. 44.	Brackets for Linear Reflective System Removal/Disposal of Existing Guardrail Special Safety Pipe Rail Miscellaneous Asphalt Paving Miscellaneous Concrete Paving Shop Bent (Radius) Miscellaneous sod installed	62.5	EA LF LF SY SY LF SF	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3.50
Total	Guardrail Cost Quote:	\$	231	8.25	
		HANDRAIL k Quote Request			
Projec	ct Name and Location				
n/a_					
ITEM	1 DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL PRICE
2 3 4 5 6 7 8	Posts 2" NPS (Sch. 40) Rails 2" NPS (Sch. 40) Rail joint/splice Handrail joint/splice Handrail 1 ½" NPS Handrail support bar 1" Mounting base plates Anchors/bolts Two rail assembly 0. Three rail assembly		LF LF EA LF LF EA LF	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	
Total	Handrail Cost Quote:		\$		
Emer	gency Response Fee		S	01-0	
Total	Project Cost Estimate:		8 0	1318.25	
	Brenda Press D. Aust 12/4/15	Contractor Representative Print DAVID M Sign De Windows Date 12315		^	

^{****} Please complete, sign, and return to Lake County





To:	Southeast Guardrail & Attn., Inc.	From:	Public Wor	ks Road Operations D	oiv.
Fax:	(561) 792-9798	Phone:	(352)	343-6439	
Phone:	(561) 792 -0040	Date:	11/4/2	2015	
E-Mail:	bmandellsga@aol.com	Pages:	3		
WORK (Road Na Guardrai Location: Nearest C Section: § Length of	604, Guardrail / Handrail Repair So QUOTE REQUEST The control of	_	<u>est</u>		
	ow many? one				
Commen		Repair aspl	ıalt base as n	<u>eeded</u>	
	s should be addressed and agreed up rmance of work.	oon in writin	g by either t	he Project Manager o	r designee prior to
Approved	l by: <u>Robert Baker</u> date: 11-4-2	2015			
County	Representative				
	Work completed OK to Pay Da	te:		Invoice #	

Approved by:

Goods Received











Lake County Property Damage - Supervisor Investigation

Lake County Board of County Commissioners

Supervisor must complete this report **immediately** following property damage.

Report must include **FULL** details concerning the property damage incident

Section I – Property Damage/Conditions/Facts

Name of Employee		Department		Division		Job Title	
Kathy wilson P		Public Works	Public Works		ıs	Office Associate	
Date of Incident Time of Incident Name of Super		Name of Superviso		Phone Numb	per of Supervisor		
unkown	N\A		Jeff Johnson		343-6439		
Name of Division D	irector (If	Applicable)		Name of Departm	ent Director		
Lori Koontz				Jim Stivender			
Specific Location o	f Incident			Type of damage			
CR 445A at SR 40				Guardrail damag	ed		
Names of all Witnes	sses N	/A	· · · · · · · · · · · · · · · · · · ·				
Supervisor Investig	jation: Ka	athy Wilson wit	h Lake County Traf			cessing and prevention. r office on 10-26-2015 that the	
damaged guardrai	l was rep	orted to her fro	om John Bringard.				

Forward completed report to the Office of Employee Services & Quality Improvement, 315 W. Main St, Admin. Building, Rm. 430 / Tavares, FL 32778.

Section II – Preventative Action

What preventative action will eliminate/minimize the risk of this type of incident again? What would employee do to prevent incident?

Examples: Written procedure, training, equipment change, corrective actions-warning/suspension to employee, , etc.

(Please attach Employee and Witness Statements, repair estimates, police reports and pictures and submit reports/forms as one packet, if possible, to Employee Services.)

Supervisor Preventative Action: