

### Recommendations:

- ✓ The existing crossings at the bus loop entrance and exit are very wide at 100 feet. To shorten crossing distances it is recommended to move existing crossing locations closer to the gates to shorten crossing distances at least at the exit. The stop sign and stop bar for the busses would also need to be moved.
- ✓ Add sidewalk to connect new crossing to existing sidewalk.

