

Priority Project #3

A SAFE SCHOOLS TRANSPORTATION STUDY Correct Drainage Issues and Repair Sidewalk at SE Corner Bound Repair Sidewalk at SE Corner

Beverly Shores Elementary School



Findings

It appears the existing on-site drainage & retention at the school may be inadequate, causing runoff and the observed washout at the sidewalk

Recommendations:

- Investigate and correct drainage issues at southeast corner and repair sidewalk at this location; likely can be corrected by restoring a proper retention area in southeast corner of school property
- Repair drainage damage
- Concrete spillway may be needed if determined erosion will continue