



Findings:

- ✓ There are two missing sections of sidewalk on Beecher St
 - ✓ Pool property, east side of street south of school property

Recommendations:

- ✓ Construct sidewalk on along the pool property on Beecher St
- ✓ Construct sidewalk on east side of street south of school property

