



A SAFE SCHOOLS TRANSPORTATION STUDY

Cypress Ridge Elementary School

Priority Project #4

Connect Sidewalk on Carroll St

Findings:

- ✓ Existing sidewalk on north side of Carroll St is interrupted just east of 2nd St by a section used for on-street parking
- ✓ It is unclear if this parking was intended to serve a particular function, but it appears out of place

Recommendations:

- ✓ Remove short on-street parking area and replace with sidewalk and landscape buffer



Carroll St at 2nd St



Carroll St at 2nd St



Carroll St at 2nd St