4345181

Lake Deaton B Continental Country Club B CR-468

NEW INTERCHANGE AT CR 468 (TPK MP 301.4) Non-SIS

Project Description:								
Work Summary:		INTERCHANGE (NEW)		From:				
				То:				
Lead Agency:		Managed by FDOT		Length:	.048 MI			
Phase	Fund Source	2014/15	2015/16	2016/17	2017/18	2018/19	Total	
PE	PKYI	30,804	0	0	0	0	30,804	
CST	PKYI	0	236,169	0	0	0	236,169	
Total		30,804	236,169	0	0	0	266,973	

Prior Year Cost:	30,619
Future Year Cost:	0
Total Project Cost:	297,592