



**To:** \_\_\_\_\_ **From: Public Works Road Operations**

**Fax:** \_\_\_\_\_ **Phone :** (352) 253-4980

**Phone:** \_\_\_\_\_ **Pages: 1**

**Re: Sod Installation** \_\_\_\_\_

---

---

**REQUEST FOR SOD INSTALLED**

**Install Date Requested:** \_\_\_\_\_

**Deliver to: Crescent Dr (3-4266B-01)**

**Section:25 Town: 19 Range:26**

**Directions to Delivery Point:** \_\_\_\_\_

**Type of sod:Bahia Quantity : 6,000 sq ft**

**Notes:** \_\_\_\_\_

Prior to performance of work, questions concerning the measurements shall be addressed and agreed upon in writing either by the Maintenance Area Supervisor or the Senior Contracting Officer. No work shall be done without an agreement. Please send invoice to the address listed below.

Please Contact us if there is a different quantity needed than what was ordered.

**County Representative:** \_\_\_\_\_

**Date:**

<b>Work completed and OK to Pay, Yes</b> <input type="checkbox"/> <b>No</b> <input type="checkbox"/>
<b>Invoice #</b>
<b>Inspected by :</b> _____ <b>Date:</b> _____

# Request Details Report

**Request Number** MA3-7118-R      **Associated Work Order** OSC-1029-WO      **Observed Date/Time** 3/11/10 2:50:P

---

## *Citizen Information*

**Name** Teresa Powell      **Phone** (352) 702-7426      **Ext.**  
**Address** 2571      **Alternate Phone**  
Crescent Dr (4266B)      **Email Address**  
Mount Dora FL

**Organization**  
**Requestor**  
**Contact**

---

## *Issue and Location*

**Activity** OSC Sod Installation      **Issue** Flooding  
**Map Page**      **Section**

**Address Number** 2571

**Route** Crescent Dr (4266B)

**Intersect Route**

## **Details**

Email from P. Hegg via D. Warren - "Flooding in yard going into her house. We built her driveway up and put swales and it is not working."

## **Notes**


Additional background details are in Request Attachments.  
For work done by Maintenance Area, see MA3-10837-WO

## **History**

3/11/2010	Check this out and see what the problem is. Give her a call. Keep me informed. I think the problem is probably a lot of rain in a very short time period and over flowed swales.	Warren, Dennis
3/11/2010	Called information to Steve on radio.	Wall, Treeva
4/1/2010	Contract sod installation requested.	Lee, Steven

**Resolution** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_


**Request Response Date** 03/11/2010 \_\_\_\_\_  
**Date** \_\_\_\_\_  
**Time Arrived** \_\_\_\_\_  
**Time Departed** \_\_\_\_\_



**JOK**

Bridge  
 Signal

0 500 1,000  
Feet



Sections

22	23	24	19
27	26	25	30
34	35	36	31

T19S - R26E  
Map Page  
17b-2526

Page  
**211**