

Request Details Report

Request Number

MA3-7515-R

Associated Work Order

Observed Date/Time

6/22/10 9:18:A

Citizen Information

Name

Billy Osborne

Phone

(352) 589-6475

Ext.

Address

19509

Alternate Phone

Spring Oak Dr (5477A)

Email Address

Eustis

FL

Organization

Requestor

Contact

Issue and Location

Activity

Issue

Drainage

Map Page

214

Section

8

Address Number 19509

Route Spring Oak Dr (5477A)

Intersect Route Park Place Bv (5477)

Details

Citizen reports an area sinking in the Right-of-Way in front of his home. Says that we have fixed it before. He says this is also causing the end of his driveway to break up.

Notes

History

6/22/2010 Issue radioed to Supervisor in field. Request has been printed. Wall, Treeva

6/22/2010 Contract pipe TV requested. Lee, Steven

Resolution _____

Request Response Date 06/22/2010

Date _____

Time Arrived _____

Time Departed _____



LAKE COUNTY
FLORIDA

To: Absolute Line Technologies **From:** John Bringard
E-mail: _____ **Phone:** 253-4980
Fax: 383-8085 **Page:** 1
Phone: 383-0002 **Date:** 6/22/2010
RE: 0 **Pipe Cleaning & Video**

WORK REQUEST

Date of Video and/or Report Due: _____
Road Name: Spring Oak Dr (5477A) **Address:** _____

Segment Number: 09

Section: 08 **Township:** 19 **Range:** 27

Location: From address 19517 going North to between addresses 19509 & 19505

Description of work to be performed: TV pipe to determine condition of pipe. Paint arrows have been marked on edge of pavement.

Pipe Size: 24 x 35 elliptical concrete pipe

Percentage of pipe blocked: 10% or less 11% - 30% above 30%

Pipe Length : 167 ft **Number of Man holes:** 1

Clean only: **TV only:** **Cleaning/TV:**

Total footage for this request : 167 ft

If there are questions concerning pipe size(s), length(s) or the % of blockage shall be addressed and agreed upon in writing by the County Representative prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Driving Directions from 19517 Spring Oak Dr Eustis, Florida to 19505 Spring Oak Dr Eustis, Flor - Windows Internet Explorer

http://www.mapquest.com/maps?lc=Eustis&ls=FL&la=19517+Spring+Oak+Dr&lz=32736-7074&ly=US&ll=28.845169&l

File Edit View Favorites Tools Help

Driving Directions from 19517 Spring Oak Dr Eustis, Fl...

360 View Traffic Street Map Aerial Map

Show labels

50 m 150 ft

Spring Oak Dr

Park Place Blvd

44B

MT. FLORIDA AIR SERVICE AIRPORT

Done Internet 100%