



LAKE COUNTY  
FLORIDA

To \_\_\_\_\_ From: **Public Works Road Operations**

Fax: \_\_\_\_\_ Phone : **(352) 343-6439**

Phone: \_\_\_\_\_ Pages: **1**

Re: **Sod Installation** \_\_\_\_\_

**REQUEST FOR SOD INSTALLED**

**Install Date Requested:** \_\_\_\_\_

**Delivery address:** CR 44A  Thrill Hill Rd

**Section:** 05 **Town:** 19 **Range:** 27 **Road Seg. #** 3-6286-05

**Directions to Delivery Point:** \_\_\_\_\_

**Type of sod:** Bahia **Quantity :** 5,600 sq ft

**Notes:** \_\_\_\_\_

Prior to performance of work, questions concerning the measurements shall be addressed and agreed upon in writing either by the Maintenance Area Supervisor or the Senior Contracting Officer. No work shall be done without an agreement. Please send invoice to the address listed below.

Please Contact us if there is a different quantity needed than what was ordered.

**County Representative:** \_\_\_\_\_

**Date:** \_\_\_\_\_

<b>Work completed and OK to Pay, Yes</b> <input type="checkbox"/> <b>No</b> <input type="checkbox"/>	
<b>Invoice #</b>	
<b>Inspected by :</b>	<b>Date:</b>

## Wall, Treeva

---

**From:** Baker, Robert  
**Sent:** Wednesday, August 24, 2011 2:16 PM  
**To:** Lee, Steve  
**Cc:** Dean, Randy; Bringard, John; Warren, Dennis  
**Subject:** Sod on CR44A

Steve;

I measured the areas on CR 44A from CR439 to 665 feet west of Thrill Hill Road that had drop offs low enough for sod. I marked the area with pink paint and we have 1,299 l.f. of road edge. You need to review what I have mark to ensure all areas are included. Please let us know how much time you will need to get the area ready for sod, as DW expressed that sod is to match the ground level of the area around it.

Thank you;.

*Bob Baker*

Contracts Coordinator  
Lake County, Road Operations  
28127 CR561  
Tavares, Fl. 32778  
Ph: (352)343-6439  
Fx: (352)742-3511  
email: [rbaker@lakecountyfl.gov](mailto:rbaker@lakecountyfl.gov)

# Request Details Report

Request Number  
MA3-8769-R

Associated Work Order

Observed Date/Time  
8/24/11 2:45:P

---

## ***Citizen Information***

Name	Phone	Ext.
Address	Alternate Phone	
	Email Address	

## Organization

Requestor Lake County Public Works  
Contact Dean, Randy

---

## ***Issue and Location***

Activity	Issue Map Page	Shoulder Section
----------	-------------------	---------------------

## Address Number

Route CR 44A (6286)

Intersect Route Thrill Hill Rd (5880)

## Details

Sod needs to be installed where shoulder work was recently done.

## Notes

## History

8/24/2011 Request has been printed and given to the Supervisor. Wall, Treeva

Resolution \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Request Response Date 08/24/2011 \_\_\_\_\_

Date \_\_\_\_\_

Time Arrived \_\_\_\_\_

Time Departed \_\_\_\_\_



