

PIPE REPLACEMENT REQUEST

REQ #: MA3-12135-R

ROAD NAME: CR 439

Address: Next apron north of the entrance to 41121

Road # 7483 Seg # 12

Sec 10

TwN 19

Rng 27

Description of Problem: Hole in the driveway apron due to pipe failure.

Description of Existing Pipe: 26' x 12" concrete

Pipe Required: 30' x 15"

Cover: Approx 18"

Bottom of culvert to ground level: 30"

Inlet/Outlet Ends: concrete mitered

Asphalt to be cut out and replaced: 11' W

Sod Required: Bahia

*S.V.*

# Request Details Report

Request Number  
MA3-12135-R

Associated Work Order

Observed Date/Time  
6/13/14 9:14:A

---

## **Citizen Information**

Name	Phone	Ext.
Address	Alternate Phone	
	Email Address	

## Organization

Requestor Lake County Public Works  
Contact Hicks, Chris

---

## **Issue and Location**

Activity	Issue Map Page	Drainage SEC	TWN	RNG
		10	19	27

Address Number 41121

Route CR 439 (7483)

Intersect Route

Details

Hole in driveway due to pipe failure.

---

## Notes

## History

6/13/2014 Contract pipe replacement requested.

Hicks,  
Christopher

Resolution \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Request Response Date 06/13/2014 \_\_\_\_\_

Date \_\_\_\_\_

Time Arrived \_\_\_\_\_

Time Departed \_\_\_\_\_

New Interactive Map Beta - We are nearing the completion of a new Interactive map which will replace this site. We encourage you to test the new site and leave us feedback to help shape its future.

[Beta test the new Interactive Map](#)

**Click here to change page title**













