



LAKE COUNTY
FLORIDA

Date: _____

Estep Construction, Inc.
689 S. Binion Road, Apopka, FL 32703

Subject: Project Order Form
Contract No. 13-0607, Storm Water Pipe/Water Quality Unit
Cleaning, Video Recording and Related Services
Purchase Order No. 20150035

Dear Estep Construction:
Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below.

Any questions or discrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778.

Pursuant to the Contract, all work shall begin within fourteen (14) calendar days from receipt of this notice. Please make sure to contact our office regarding the scheduling of this work.

PIPE LOCATION: Road Number: 7804 Segment Number: 4

Road Name: CR 25 Address: N/A

Section: 17 Township: 18 Range: 24 Closest City: Lady Lake

PIPE SPECIFICATIONS:

Diameter: 18" Length: 43.5 Number of Manholes/Inlets: _____

Percentage of Blockage: 10% or less 11% - 30% above 30% X

WORK DESCRIPTION:

Pipe is completely clogged, pipe is located on CR 25 in front of Duke Sub Station
underneath the north driveway on the east side of CR 25.

Work Completed and OK to PAY: _____	Invoice # _____
Inspected by _____	Date _____

Request Details Report

Request Number MA1-11038-R Associated Work Order MA1-20329-WO Observed Date/Time 7/13/16 2:01:P

Citizen Information

Name _____ Phone (352) 751-1526 Ext. _____
Address _____ Alternate Phone _____
Email Address _____

Organization City of Lady Lake

Requestor _____

Contact Peggy

Issue and Location

Activity SHD Build-Up Shoulder Issue _____ Washout _____
Map Page _____ SEC TWN RNG

Address Number _____

Route CR 25 (7804)

Intersect Route HWY 441

Details

Peggy with the City of Lady Lake called and reported that water run-off from the overpass of Hwy 441/27 has created a bas washout on CR 25 which is underneath the overpass.

Notes

History

Resolution _____

Request Response Date 07/13/2016