| PIPE | REDI | ACEN | JENT | REO | LIEST |
|------|------|------|-------------|-----|-------|
| | | | | | |

REQ #: MA3-14871-R

ROAD NAME: CR 46A

Address: 28214 CR 46A, Sorrento

Road # 4891

Seg # 04

 Sec
 25

 Twn
 19

 Rng
 28

Description of Problem: Bottom of pipe is rusted out.

Description of Existing Pipe: 24" x 40' CMP

Pipe Required: 24' x 40' L

Cover: concrete

Bottom of culvert to ground level: 28"

Inlet/Outlet Ends: mitered ends

Asphalt to be cut out and replaced: Concrete: 8'D x 21' 5" W

5. Sod Required: Bahia

Request Details Report

| MA3-14871-R | 9/1/16 12:43:P |
|--|--|
| Citizen Information Name Address | Phone Ext. Alternate Phone Email Address |
| ganization Requestor Lake County Public World Contact McCall, Truman | -ks |
| Issue and Location Activity | Issue Drainage Map Page SEC TWN RNG 25 19 28 |
| Address Number 28214 | |
| Route CR 46A (4891) | |
| Intersect Route Details Bottom of pipe is rusted out. | |
| Notes | |
| History | |
| Resolution | |
| | |
| Request Response Date 09/01/2016 | |
| Date Time Arrived | |
| Time Departed | |





