


To:	From: Publ	<u>ic Works/Road Ops</u>
Fax:	Pages:	1
Phone:	Date:	1/11/2017
E-Mail:		
TREE REMOVAL REQUEST	<u>F</u>	
Road Name: Country Club Dr Se Nearest City:Eustis Address: 1901 Section 13 Township: 19 Description of Tree: Oak Location of Tree: At address # 19 Size of tree (s): 37" Grind Stump? Remore If trim what class? Class 1 Power Lines or other hazards invested to the comments: Requesting Arborist's	Range: 26 901 ve Stump? Class 2 olved? Yes Type of soc	Class 3 No
Questions concerning tree size(s) shall be ac or designee prior to the performance of the	ddressed and agre work. Any work p	ed upon in writing by either the Project Manager erformed without agreement by all parties shall be act. Invoices should be sent to the address listed
Approved by:	Date:	
County Representat		
Work Completed and OK to I	Pay: Yes	No
Inspected by:		Date:
HIRITAN HIRIO COM AND		

Request Details Report

Request Number MA3-15172-R			Observed Date/Time 1/11/17 9:45:A		
Citizen Information Name Address	Al	none Iternate Phone nail Address		Ext.	
Organization Requestor Lake County P Contact Lee, Steve	ublic Works				
Issue and Location Activity		Issue Map Page	Tree F SEC 13	Removal TWN 19	RNG 26
Address Number 1901					
Route Country Club Dr (5	(268)				
Intersect Route Details Requesting Arborist's opinion of	of a 37" Oak - Seg 02				
Notes					
History					
Resolution					
Request Response Date					
Time Departed					







Wall, Treeva

From:

Lee, Steve

Sent:

Tuesday, January 10, 2017 3:30 PM

To:

Wall, Treeva; Lee, Steve

Subject:

Oak tree

Attachments:

20170110_152553_resized.jpg; 20170110_152546_resized.jpg; 20170110_152538

_resized.jpg

Treeva

Need to do the paperwork up to have an arborist check out the tree at 1901 Country Club Drive Eustis

Sent from my Sprint Samsung Galaxy S® 6.

垂

37" 00





