

Stormwater inspector looked at the pipe ... there is fresh disturbance in the area – a bag of riprap looks like it was pulled out of the pipe.

Both headwalls are covered with dirt.

Suspect that both headwalls need to be replaced, but won't know exactly until they are unearthed.

Pipes need to be cleaned.

Erosion is the dirt that has slowly, over time, washed down and covered the headwalls.