

Fax: 407-884-6904 689 Binion Road Apopka, FL 32703

APR -8 2015

CC/Ship To:

1	n	V	O	Ī	C	e
---	---	---	---	---	---	---

Date	Invoice #
4/6/2015	605

Bill To

Lake County PW
Road Operations
12901 County Landfill Rd
Tavares, FL 32778

Contract #13-0607 mod 1 PO #20150035 34253 Woodbridge Lane 35649 CR 439

P.O./Contract #	Terms	Due Date	Ship Date	Ship Via	Project
20150035	Due on receipt	4/6/2015	4/6/2015		14-16/AP

		Т.						
Item		Description	Qı	uantity		Unit I	Pr	Amount
1	34253 Woodri Video Recording 34 35649 CR 439		512	2	LF		1.00	512.00
1	Video Recording 15		39)	LF		1.00	39.00
					gr.	5/8/	15	
			PO#: Acct	#: 11	CONS' 150035 20.5053	3200.8	TION 30460	
Thank you for yo	ur business.		 <u>j</u>	То	tal			\$551.00

Balance Due

\$551.00

BP 9 1/7/15 x 64-09-15



Date

Estep Construction, Inc. 689 S. Binion Road, Apopka, Fl. 32703

Subject:

Project Order Form

Contract No. 13-0607, Storm Water Pipe/Water Quality Unit

Cleaning, Video Recording and Related Services

Purchase Order No. 20131369

Dear Estep Construction:

Please find below a request for services under the Storm Water Pipe/Water Quality Unit Cleaning, Video Recording and Related Services Contract No. 13-0607. A description of the requested services and project specific information is listed below.

Any questions or descrepancies regarding the pipe size, length or amount of blockage must be addressed and agreed upon between the Contractor and the Project Manager prior to performing any work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to 12901 County Landfill Road, Tavares, FL 32778.

Pursuant to the Contract, all work shall begin within fourteen (14) calendar days from receipt of this notice. Please make sure to contact our office regarding the scheduling of this work.

Road Name: Spring Oak Dr 3-5477A-0		34253 Woodridge Ln	
	19 Ran		
Section: 8 Township:	,,,,,	ge: <u>27</u>	
PIPE SPECIFICATIONS:		*	
Diameter: 34" Length:	~500 ft Number	r of Manholes/Inlets:	2
Percentage of Blockage: 1.0% or less	N/A 11% - 30	0% above 30%	
WORK DESCRIPTION:	to a second and debugge	au hardantar ta cava in	
TV only. Please complete ASAP - there i	s a concrete drivew	ay beginning to cave iii.	
Work Completed and OK to PAY:		Invoice No.	
Inspected by		Date	

Request Details Report

Request Number MA3-13092-R		Associated Work	3/9/15 9:54:A				
Citizen II Name Address	John O'To 34253 Woodridge Lr Eustis		Phone (352 Alternate Ph Email Addres		Ext.		
Organization Requestor Contact	•						
Issue and Activity	d Location		Issue Map Pag	Drain SEC	-	RNG	
Details Citizen repo	orts that the pipe u	ınder his driveway is	s collapsing.				
Notes							
History 3/10/2015		tv requested.			Lee, S		
						Steven	
F	Resolution			,		Steven	

We are working on a new Interactive Map that will replace this site. We encourage you to test the new site and leave us feedback to help shape its future. Beta test the new Interactive Map.

Click here to change page title

