

## Invoice

Date	Invoice #		
9/10/2015	6273		

LAKE COUNTY PUBLIC WORKS PO BOX 7800 TAVARES, FL 32778

RECEIVE

SEP 21 2015

LAKE COUNTY ROAD OPERATIONS

Project Description	GUARDRAIL REPAIR
Contract #	
Financial Project #	G3047-C
Dates of Service/ Date of Completion	
Location	CR 561

Work Order No

Item No	Quantity	Description	U/M	Unit Price	Total
MISC LF MISC LF MISC EACH MISC EACH MISC LF	37.5 37.5 3 37.5 3 37.5	RE-ALIGNMENT OF EXISTING GUARDRAIL GUARDRAIL PANEL OFFSET BLOCKS REMOVAL AND DISPOSAL OF EXISTING GUARDRAIL MISC PAVING	LF LF EA LF	3.00 9.00 8.00 1.00 21.00	112.50 337.50 24.00 37.50 63.00
				OK TO PAY -	*
			PO#: Acct#: Goods	201500 1120.5053200. Recd: 9 /	830467
		CONTRACTOR'S SIGNATURE:			
		CONTINUED ON THE STATE OF THE S	Bala	ance Due	\$574.50

FDOT DBE CERTIFIED
PALM BEACH COUNTY SWBE CERTIFIED

9/23/15

BP

9/23/15

and Hit



10.	Southeast Guardran & Attn., Inc.	From:	Public Wo	rks Road Operations I	Dív.
Fax:	(561) 792-9798	Phone:	(352)	343-6439	
Phone:	(561) 792 -0040	Date:	8/4/2015		
E-Mail:	csinkussga@aol.com	Pages:	3		
					Add the same of th
Re: 11-0	604, Guardrail / Handrail Repair S	<u>ervice Reque</u>	<u>est</u>		
WORK (	QUOTE REQUEST				
Road Na	ime: CR 561 Segment Number: 2-30	047-08			
Guardra	il Number: <u>G3047-C</u>				
Location	: North of Turnpike near Shiloh Acr	es Drive			
Nearest (	City: <u>Minneola</u>				
Section: §	3 Township: 21 Range: 26				
Length o	f damage if not an end: 37.5' feet				
	naged? Yes 🗌 No 🔯				
If yes, h	ow many?				
Commen <u>Please ke</u>	ts: <u>Repair asphalt base as neede</u> ep this repair information seperated,	d, This sectio	n was repai	red by Southeast per	in voice #5963.
Questions the perfo	s should be addressed and agreed up rmance of work.	on in writing	g by either t	he Project Manager o	or designee prior to
Approved	i by: <u>Robert Baker date : 7-28-20</u>	015	, , , , , , , , , , , , , , , , , , ,		
County 1	Representative				
	Work completed OK to Pay Dat	e: 9-10	0-15	Invoice#	10772
	Approved by:	Z	The second second	Goods Received	02/3
	- was a second of the second o				9-10-13
					L



To:	Southeast Guardrail & Attn., Inc.	From: Public Works Road Operations Div.			iv.	
Fax:	(561) 792-9798	Phone:	e: (352) 343-6439			
Phone:	(561) 792 -0040	Date:	7/29/2015			
E-Mail:	csinkussga@aol.com	Pages:	3			
Re: 11-0604, Guardrail / Handrail Repair Service Request  WORK QUOTE REQUEST  Road Name: CR 561 Segment Number: 2-3047-08  Guardrail Number: G3047-C  Location: North of Turnpike near Shiloh Acres Drive  Nearest City: Minneola  Section: 8 Township: 21 Range: 26  Length of damage if not an end: 37.5' feet  Ends damaged? Yes \( \sum \) No \( \sum \)						
If yes, ho	ow many?					
Comments: Repair asphalt base as needed, This section was repaired by Southeast per in voice #5963. Please keep this repair information seperated.						
Questions should be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of work.						
Approved by: Robert Baker date: 7-28-2015						
County Representative						
	Work completed OK to Pay Da	te:		Invoice #		
	Approved by:			Goods Received		

## Guardrail Work Quote Request All prices include installation

Project Name and Location

Contractor

G304	7-C, CR 561 ( wid )		Southe	ast Guardrail
ITEA	1 DESCRIPTION	QUANTITY	UNIT	UNIT TOTAL PRICE
4 4 4-17	1 BESCRIPTION	QUANTITI	OMI	TRICE TRICE
1.	Resetting Guardrail (Single Face)		LF	\$\$
3	Resetting Guardrail (Double Face)		LF	\$S
(3)	Re-alignment of existing guardrail	37.5	LF	\$ 3 \$ 112.5
4.	New Guardrail-Including Post, Offset Blocks,			
(3)	Reflectors, Delineator Assemblies, Hardware etc.	17 0	LF	\$ 5
(3)	Guardrail Panels Guardrail Posts	37-5	LF	s 9. s 337.50
5 6. 7 8. 9.	Encased Guardrail Post		EA	\$ \$
(8)	Offset Blocks	0	EA	S S
0.	Special End Shoes	3	EA EA	s 8 s 24.00
10.	Terminal Connector		EA	\$
11.	Flared End Section		EA	\$ \$
12.	Half Rounded End Section		EA	\$ \$
	That Rounded End Section		LA	3
13.	Full Rounded Buffer End Section		EA	\$ \$
14.	Anchor Plate Assembly		EA	S S
15.	Type II End Anchorage Assembly		EA	\$ \$
16.	End Anchorage Assembly Type MELT	And a second sec	EA	\$ S
17.	End Anchorage Assembly Type CRT		EA	\$ \$
18.	End Anchorage Assembly Type ET-2000		EA	\$ \$
19.	End Anchorage Assembly Type SRT-350			
	(8 post system)		EA	\$ \$
20.	End Anchorage Assembly Type BEST		EA	\$ \$
21.	End Anchorage Assembly Type LET		EA	\$\$
22.	End Anchorage Assembly Type SKT-350		EA	\$ \$
23.	End Anchorage Assembly Type FLEAT-350		EA	\$\$
24.	End Anchorage Assembly Type REGENT		EA	\$ \$
25.	Repair Existing Bridge End Assembly		EA	\$ \$
26.	Steel Anchor Post (Bridge)		EA	\$\$
27. 28.	Concrete Anchor Post (Bridge)	-	EA	\$\$_
29.	End Post with Special End Shoe Recess (Bridge)		EA	\$\$
47.	Special Steel Guardrail Post for Single or double face Guardrail (where culverts or other structures preclude	S		
	Normal installation).		EA	\$ \$
30.	Transition Panel from trie-beam to w-beam		EA	\$ \$
31.	Detail J Bridge Anchorage		EA	\$ \$
32.	ET 2000 Extruder Head		EA	\$ \$
33.	SKT - 350 Extruder Head		EA	S S
34.	FLEAT 350 Extruder Head		EA	\$ \$
35.	Reflectors		EA	\$ \$
36.	4" Linear Reflective System		EA	\$ \$
37.	(include the manufacture type and specifications)		*1.2	
J. J.	6" Linear Reflective System		EA	8
	(include the manufacture type and specifications)			

38. Brackets for Linear Reflective System 39. Removal/Disposal of Existing Guardrail 40. Special Safety Pipe Rail 41. Miscellaneous Asphalt Paving 42. Miscellaneous Concrete Paving 43. Shop Bent (Radius) 44. Miscellaneous sod installed	37-5 LF \$ 1. \$ 37.5  LF \$ 5  SY \$ 31. \$ 53.00  SY \$ 5  LF \$ 5  SF \$ 5
Total Guardrail Cost Quote:	s 574.50
Wo	HANDRAIL ork Quote Request
Project Name and Location	
n/a	
ITEM DESCRIPTION	QUANTITY UNIT PRICE PRICE
<ol> <li>Posts 2" NPS (Sch. 40)</li> <li>Rails 2" NPS (Sch. 40)</li> <li>Rail joint/splice</li> <li>Handrail joint/splice</li> <li>Handrail 1 ½" NPS</li> <li>Handrail support bar 1"</li> <li>Mounting base plates</li> <li>Anchors/bolts</li> <li>Two rail assembly</li> <li>Three rail assembly</li> </ol>	LF \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
Total Handrail Cost Quote:	\$
Emergency Response Fee	\$
Total Project Cost Estimate:	\$ 574.50
County Representative Print Brenda Press Sign Bress Date 8/20/20/5	Contractor Representative  Print DAVID on RICCI  Sign Dal M  Date 8 117 115

\*\*\*\* Please complete, sign, and return to Lake County

G3047-C, CR561 07.24.2015 12:30







