

ROAD OPERATIONS

# Invoice

Date	Invoice #		
7/8/2015	5962		

Bill To	
LAKE COUNTY PUBLIC WORKS PO BOX 7800 TAVARES, FL 32778	RECEIVED , JUL 1 0 2015
	LAKE GOUNTY

Project Description	GUARDRAIL REPAIR
Contract #	
Financial Project #	G3047-E
Dates of Service/ Date of Completion	
Location	CR 561

Work Order No

Item No	Quantity	Description	U/M	Unit Price	Total
MISC LF MISC LF MISC EACH MISC LF MISC SY	50 50 7 50 5 5	RE-ALIGNMENT OF GUARDRAIL GUARDRAIL PANEL OFFSET BLOCKS REMOVAL MISC PAVING  RECEIVED  JUL 10 2015  PUBLIC WORKS DEPARTMENT	LF LF EA LF sqyd	3.00 9.00 8.00 1.00 21.00 OK TO PAY - 2015 004 1120.5053200. Recd: 9 /s	150.00 450.00 56.00 50.00 105.00
		CONTRACTOR'S SIGNATURE:			
			Balaı	nce Due	\$811.00

K OTTOIS

FDOT DBE CERTIFIED
PALM BEACH COUNTY SWBE CERTIFIED

# Guardrail Work Quote Request All prices include installation

Project Name and Location

G3047-E, CR 561

Contractor

<u>G30</u>	47-E, CR 561	SEA			
ITE	M DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAI PRICE
1.	Resetting Guardrail (Single Face)		LF	\$ \$	
2.	Resetting Guardrail (Double Face)	Pro Print Constitution of the Constitution of	LF	\$\$	
3.	Re-alignment of existing guardrail	.50	LF		50 00
4.	New Guardrail-Including Post, Offset Blocks,			***************************************	
	Reflectors, Delineator Assemblies, Hardware etc.		ĹF	\$ \$	
5.	Guardrail Panels	_50	LF	\$9 \$-	150.00
6.	Guardrail Posts		EA	\$\$	
7.	Encased Guardrail Post		EA	\$\$	
8.	Offset Blocks		EA	\$ 8 5	56.00
9.	Special End Shoes	***************************************	EA	\$\$_	
10.	Terminal Connector		EA	\$\$_	
11.	Flared End Section	<u> </u>	EA	\$\$_	
12.	Half Rounded End Section		EA	\$\$	
13.	Full Rounded Buffer End Section		EA	\$\$_	
14.	Anchor Plate Assembly		EA	\$ \$	
15.	Type II End Anchorage Assembly		EA	\$ \$	
16.	End Anchorage Assembly Type MELT		EA	\$\$	
17.	End Anchorage Assembly Type CRT		EA	\$\$	
18.	End Anchorage Assembly Type ET-2000		EA	\$\$	
19.	End Anchorage Assembly Type SRT-350				
	(8 post system)	Branch	EA	\$\$_	
20.	End Anchorage Assembly Type BEST	Randon de la companyone de	EA	\$\$	
21.	End Anchorage Assembly Type LET	31177 \$1170 CO. (1910 CO.	EA	\$\$_	
22.	End Anchorage Assembly Type SKT-350		EA	\$\$_	
23.	End Anchorage Assembly Type FLEAT-350		EA	\$\$_	
24.	End Anchorage Assembly Type REGENT	P-0-754070 4-45000120-10-4	EA	\$\$	
25.	Repair Existing Bridge End Assembly		EA	\$\$	
26.	Steel Anchor Post (Bridge)	200000000000000000000000000000000000000	EA	\$\$	
27.	Concrete Anchor Post (Bridge)	And the second s	EA	\$\$_	
28.	End Post with Special End Shoe Recess (Bridge)	F	EA	\$\$	
29.	Special Steel Guardrail Post for Single or double face Guardrail (where culverts or other structures preclude	28			
20	Normal installation).		EA	\$\$	
30.	Transition Panel from trie-beam to w-beam		EA	<b>\$\$</b>	
31.	Detail J Bridge Anchorage		EA	\$\$	
32.	ET 2000 Extruder Head		EA	\$\$	***
33.	SKT – 350 Extruder Head		EA	\$\$	
34.	FLEAT 350 Extruder Head		EA	\$\$	
35.	Reflectors	×	EA	\$\$_	
36.	4" Linear Reflective System		EA	\$\$	
27	(include the manufacture type and specifications)		*** (	<b>.</b>	
37.	6" Linear Reflective System		EA	\$\$	
	(include the manufacture type and specifications)				

38. 39. 40. 41. 42. 43.	Brackets for Linear Reflective System Removal/Disposal of Existing Guardrail Special Safety Pipe Rail Miscellaneous Asphalt Paving Miscellaneous Concrete Paving Shop Bent (Radius) Miscellaneous sod installed	.50		EA LF LF SY SY LF SF	\$ \$	50 00 05:00
Total	Guardrail Cost Quote:		\$	81 Albo	P 6-3-1	15
	,	HANDRAIL Work Quote Reques	st	·		
Projec	et Name and Location					
n/a		Anti-Courte Court Charles				
ITEN	1 DESCRIPTION	QUA	NTITY	UNIT	UNIT PRICE	TOTAL PRICE
1 2 3 4 5 6 7 8 9	<ul> <li>Rails 2" NPS (Sch. 40)</li> <li>Rail joint/splice</li> <li>Handrail joint/splice</li> <li>Handrail 1 ½" NPS</li> <li>Handrail support bar 1"</li> <li>Mounting base plates</li> <li>Anchors/bolts</li> </ul>			LF LF EA LF LF EA EA LF	\$\$ \$\$	
Total	Handrail Cost Quote:			\$		
Emer	gency Response Fee			\$		8.
<u>Total</u>	Project Cost Estimate:			\$	811.0	0
Print Sign	(1211)					
Date	· 1	Date				

<sup>\*\*\*\*</sup> Please complete, sign, and return to Lake County



To:	Southeast Guardrail & Attn., Inc.	From:	Public Works Road Operations Div.		
Fax:	(561) 792-9798	Phone:	(352) 343-6439		
Phone:	(561) 792 -0040	Date:	5/28/2015	***	
E-Mail:	csinkussga@aol.com	Pages:	3		
	i04, Guardrail/Handrail Repair Se	rvice Reque	<u>st</u>		
`	UOTE REQUEST				
	me: <u>CR 561</u> Segment Number: <u>2-30</u>	147-09			
	l Number: <u>G3047-E</u>			•	
Location:	East shoulder just past Holman Lee	Road on CR	<u>561</u>		
Nearest C	ity: Minneola				
Section: 8	Township: <u>21</u> Range: <u>26</u>				
Length of	damage if not an end: Two (2) sect	ions 26' feet	<u>each</u>		
Ends dam	nged? Yes 🔲 No 🗵	-			
If yes, he	ow many?				
Comment	s: Repair asphalt base as neede	<b>d</b>			
	should be addressed and agreed up	on in writin	g by either the Project Manager or desig	gnee prior to	
Approved by: Robert Baker date: 4-14-2015					
County 1	Representative				
	Work completed OK to Pay Dat	e:	Invoice #		
	Approved by:		Goods Received		



To:	Southeast Guardrail & Attn., Inc.	From:	Public Worl	ks Road Operations D	iv		
Fax:	(561) 792-9798	Phone:	(352) 3	343-6439			
Phone:	(561) 792 -0040	Date:	4/14/2	015	AA AA		
E-Mail:	csinkussga@aol.com	Pages:	3		<u> </u>		
Re: 11-0604, Guardrail / Handrail Repair Service Request  WORK QUOTE REQUEST  Road Name: CR 561 Segment Number: 2-3047-09  Guardrail Number: G3047-E  Location: East shoulder just past Holman Lee Road on CR 561  Nearest City: Minneola  Section: 8 Township: 21 Range: 26  Length of damage if not an end: Two (2) sections 26' feet each							
Ends dan	naged? Yes 🗌 No 🔀						
If yes, he	ow many?						
Comment	s: Repair asphalt base as neede	<u>d</u>					
Questions should be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of work.							
Approved by: Robert Baker date: 4-14-2015							
County Representative							
	Work completed OK to Pay Da	te:		Invoice #			
	Approved by:			Goods Received			

#### Press, Brenda

From:

Press, Brenda

Sent:

Wednesday, May 27, 2015 9:20 AM

To: Cc: 'David Ricci' Baker, Robert

Subject:

RE:

#### Good morning David,

Thank you for sending the quotes to repair the various guardrails on CR 561. Two of the four quotes have incorrect pricing based on the contract (Contract No. 11-0604C). Please revise the quotes for G3047-D and G3047-E as outlined below. Thank you!

- The quote for G3047-D has an incorrect price for offset blocks (Line No. 8). The correct contract price for offset blocks is \$8.00 each. Please reduce this line item by \$1,197.00. The guardrail posts (Line No. 6) should be charged at \$65.00 each. Please increase this line item by \$195.00. The total repair cost for this guardrail should be \$2,185.00.
- The quote for G3047-E has an incorrect price for offset blocks (Line No. 8). The correct contract price for offset blocks is \$8.00 each. Please reduce this line item by \$49.00, for a total repair cost of \$811.00.

Should you have any questions, comments or require additional information, please do not hesitate to call or email my office. Thank you!

### Brenda l. Press

Contracting Officer I

#### Lake County Department of Public Works, Road Ops Division

12901 County Landfill Road

Tavares, FL 32778 T: (352) 343-6439

F: (352) 742-3888

bpress@lakecountyfl.gov

Please note: Florida has a very broad public records law. Most written communication to or from government officials regarding government/public business is public record available to the public and media upon request. Your e-mail communications may be subject to public disclosure.

From: David Ricci [mailto:goquads@aol.com]

**Sent:** Monday, May 04, 2015 7:30 AM

To: Baker, Robert Cc: Press, Brenda

Subject:

Sincerely, David Ricci Southeast Guardrail



CR561, G3047-E 04.10.2015 13:46





#### Press, Brenda

From:

Press, Brenda

Sent:

Wednesday, September 23, 2015 10:20 AM

To:

Csinkussga@aol.com; David Ricci (goquads@aol.com)

Cc:

Johnson, Jeff; Baker, Robert

Subject:

FW: Outstanding Guardrail Repairs/Invoicing

Importance:

High

## Good morning David/Connie -

Please see below email that was sent back in July regarding our inability to process some of the invoices because the asphalt work was not completed. Invoice Nos. 5962 and 5964 cannot be processed as submitted because the asphalt paving was not done. Please do not submit these invoices again until the asphalt paving has been completed.

Please note that pursuant to Contract No. 11-0604C between Southeast Attenuators and Lake County there is language provided to assess the contractor a re-inspection fee of \$80 per inspection required after the initial inspection due to deficiencies or incomplete work. This language can be found in Exhibit C, General Terms and Conditions; Section 20, Final Inspection; Paragraph C.

Thank you in advance for your prompt attention to this matter.

# Brenda l. Press

Contracting Officer I

Lake County Department of Public Works, Road Ops Division

12901 County Landfill Road

Tavares, FL 32778

T: (352) 343-6439

F: (352) 742-3888

bpress@lakecountyfl.gov

Please note: Florida has a very broad public records law. Most written communication to or from government officials regarding government/public business is public record available to the public and media upon request. Your e-mail communications may be subject to public disclosure.

From: Press, Brenda

Sent: Wednesday, July 29, 2015 8:24 AM

To: David Ricci (goguads@aol.com); 'csinkussga@aol.com'

Cc: Baker, Robert; Johnson, Jeff

Subject: Outstanding Guardrail Repairs/Invoicing

Importance: High

### Good morning David,

My office received the following invoices (5962, 5963, 5964, and 5965) for the guardrails (G3047C-F) on CR 561. We cannot process these invoices at this time because the asphalt paving at the base of the posts has not been completed. The damage at the end of guardrail G3047C has not been completed either. Please coordinate with Bob Baker when these repairs are going to be completed so we can re-inspect the sites and process these invoices.

There has been another accident to the guardrail G3047C which is located in one of the newly repaired areas, which did not have the asphalt bases completed. Since the asphalt repair has not been completed, we can remove the cost for the asphalt paving from the last invoice 5963, but the work would need to be completed on all posts on the next repair. Bob will send you the paperwork for the newly damaged area, please send a quote so we can approve and possibly schedule

all repairs for the same time. The repair for the new damage on guardrail G3047C will need to be quoted separately from the previous work orders.

Please call my office to discuss how you would like to proceed with resolving these outstanding issues. I will be leaving for vacation this afternoon, so if you cannot call prior to that, please speak with Bob Baker. He can be reached at (352) 343-6439 or (352) 308-9784. Thank you in advance for your assistance in resolving these outstanding items.

#### Brenda l. Press

Contracting Officer I

Lake County Department of Public Works, Road Ops Division

12901 County Landfill Road Tavares, FL 32778 T: (352) 343-6439 F: (352) 742-3888

bpress@lakecountyfl.gov

Please note: Florida has a very broad public records law. Most written communication to or from government officials regarding government/public business is public record available to the public and media upon request. Your e-mail communications may be subject to public disclosure.

