

Recommended Project #2

Crosswalk Improvements

Findings:

- ✓ Most walkers were observed to come and go from the neighborhood across the street from the school
- ✓ Several cross streets were missing crosswalks, ramps, and sidewalk connections

Recommendations:

- ✓ Install crosswalks on all cross streets along Magnolia St from Main Ave to SR 33
- ✓ Construct ramps with detectable warning maps at all cross streets along Magnolia St from Main Ave to SR 33
- ✓ Construct missing sidewalk segments along Magnolia St from Main Ave to SR 33

