



A SAFE SCHOOLS TRANSPORTATION STUDY

Cecil E. Gray Middle School

Priority Project #3

Relocate Existing Main Crosswalk

Findings:

- ✓ The existing crosswalk provided at the main entrance does not line up with the sidewalk used by students at dismissal
- ✓ Existing crosswalk endpoint is a residential driveway

Recommendations:

- ✓ Move existing crosswalk south to line up with sidewalk
- ✓ Install pavement markings and relocate signage to new crossing

