



A SAFE SCHOOLS TRANSPORTATION STUDY

Cypress Ridge Elementary School

Priority Project #5

Sidewalk Repair/Maintenance

Findings:


- ✓ Portions of the existing sidewalks on East Ave (west side) and 2nd Street adjacent to the school are in poor condition – overgrown and cracked
- ✓ Cracked sidewalks can be a tripping hazard

Recommendations:

- ✓ Repair and maintain sidewalks as necessary



East Ave Sidewalk south of the school driveway



2nd St Sidewalk south of Oak St