



A SAFE SCHOOLS TRANSPORTATION STUDY

Cypress Ridge Elementary School

Priority Project #6


Replace/Update Signage at Drop-off / Pick-up Loops

Findings:

- ✓ Existing signs at exit of front drop-off / pick-up loop to East Ave is worn
- ✓ Sign noting times of left turn prohibition is not legible
- ✓ “Do Not Enter” signs at both drop-off / pick-up loop exits is non-standard

Recommendations:

- ✓ Replace signs at East Ave driveway exit
- ✓ Use standard MUTCD R5-1 “Do Not Enter” signage at both drop-off / pick-up exit driveways



East Ave school exit



East Ave exit