SafeAccess A SAFE SCHOOLS TRANSPORTATION STUDY **Grassy Lake Elementary School**

Priority Project #3

Westbound Fosgate Rd queue (PM)



Westbound Fosgate Rd queue (AM)

Findings:

During dismissal, westbound vehicles waiting to enter the car pick-up loop were observed to queue back on Fosgate Rd for 900 feet

Westbound Right Turn Lane into Car Loop Driveway

- There is a sight distance issue with the hill on Fosgate Rd east of the school
- Westbound through vehicles use center turn lane to pass queued vehicles; cross-over point creates conflicts & is a safety hazard
- Existing landscape strip is about 14 feet wide
- ✓ There are no drainage inlets along the curb in this area
- Some utility poles would need to be relocated

Recommendations (Option 1):

 Constructing a westbound right turn lane of 200-400 feet would help mitigate the safety hazard created by westbound through vehicles by moving the cross over point away from the driveway and other conflicting vehicles