


Findings:

- ✓ Pedestrian walkway is currently painted on the pavement
- ✓ Buses line up like a “horseshoe”



Recommendations:

- ✓ Extend the sidewalk in front of the chillers; provide driveway on “diagonal” portion to allow access to the chillers
- ✓ Extend the sidewalk from the chillers to the bus loop exit; permanently remove parking spaces currently marked with painted walkway (i.e. fill in with grass and raised curbing)