



SafeAccess

A SAFE SCHOOLS TRANSPORTATION STUDY

Minneola Elementary Charter School

Priority Project #3

School Driveway Crosswalks

Findings:

- ✓ Front school driveway on Pearl St has faded crosswalk markings and detectable warnings missing on west side of crosswalk
- ✓ Bus driveway on Grassy Lake Rd does not have a marked crosswalk

Recommendations:

- ✓ Restripe crosswalk at Pearl St driveway and install missing detectable warnings
- ✓ Stripe crosswalk at Grassy Lake Rd bus driveway



Pearl St school driveway



Grassy Lake Rd school bus driveway

