## PIPE REPLACEMENT REQUEST

Road Name:

First St

Road #: 9689B Segment #: 01

At Intersection: Butler St

Road #: 8990

Section: 37

Township: 15 Range: 28

Road is collapsing due to pipe failure. We will effect a temporary repair.

Pipe required: 63 ft. of 18 inch pipe

Cover: 42 inches from ground to top of pipe.

Inlet/Outlet Ends: concrete mitered ends

Asphalt Cut-Out Across Road: 10 ft wide x 26 ft across.

## Request Details Report

Request Nur MA3-6986-		Associated Work Order OSC-998-WO		<b>Observed Date/Time</b> 2/10/10 11:35:A	
Citizen Inf Name Address				ne ne ss	Ext.
Contact (	ake County Of Harmon v Shannon	Sheriff's Office via			
Issue and Activity	Location		Issue Map Page 25	Edge of Paver Section 37	ient
Address N	umber				
Route First	St (9689B)				
Details	ening up under	r St (9690) the road.			
Notes	hu Maintanan	no Arno Con MAD 4004	2.14/0		
For Work done	e by Maintenan	ce Area, See MA3-1064:	3-VVO.		
History					
2/10/2010	Request has I	peen printed and given to	the Supervisor.	Wall, Treeva	
2/12/2010	Requested co	ntract pipe replacement.		Dean, Randy	(
Res	solution				
-					
Request Resp	Date	10/2010			
Time	e Departed				

