

То:	From: Pub	lic Works/Road Ops
Fax:	Pages:	1
Phone:	Date:	11/5/2012
E-Mail:		
TREE REMOVAL REQUES	<u>ST</u>	
Road Name: Cherry Ln Segment Nearest City: Mount Dora Address: 1721 Section 28 Township: 19 Description of Tree: Oak Location of Tree: in ROW Size of tree (s): 40" Grind Stump? yes Remove Some Sod? Yes Remove Sod? Yes No Comments:  Ouestions concerning tree size(s) shall to redesignee prior to the performance of paid in accordance with the terms and concerning tree size(s).	Range: 27  tump? Class 2  nvolved? Ye Type of	Class 3
Approved by:  County Represe	<u>Date</u>	2:
Work Completed and OK Inspected by:		No Date:
Invoice #		

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.

Mailing Address, PO Box 7800, Tavares Florida 32778,

Phone Number: 352-343-6439 – Fax Number: 352-742-3888

Revised: 6-29-2012

## Request Details Report

Request Number Associated Work Order VIA3-10221-R		Observed Date/Time 11/2/12 2:24:P	
Citizen Information Name Heidi Sommer Address 1710 Heather St (4480 Mount Dora	Alternate DB) Email Ad		Ext.
rganization			
Requestor Contact			
Issue and Location Activity	Issue Map 223	Page Sect 27	Removal <b>ion</b>
Address Number			
Route Cherry Ln (4480A)			
Intersect Route Details Citizen reports a dead tree in the Notes	∋ ROW at her neighbor's hous	e, across the road	from her address.
History 11/2/2012 Request has been	en printed and given to the Su	pervisor.	Wall, Treeva
Resolution ———			
No Power line	Tree is at 1721		
1044 40" Oak	, wo sol		

## Click here to change page title





