



LAKE COUNTY
FLORIDA

To: _____ From: **Public Works/Road Ops**

Fax: _____ Pages: **1**

Phone: _____ Date: **6/11/2013**

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Arlington Av Segment No.: 3-4388D-01

Nearest City: Sorrento

Address: 25725 Colmar Av (Tree is on Arlington)

Section 29 Township: 18 Range: 28

Description of Tree: oak

Location of Tree: On Arlington, side of address above.

Size of tree (s): 23"

Grind Stump? yes _____ Remove Stump? _____

If trim what class? Class 1 Class 2 Class 3

Power Lines or other hazards involved? Yes No

Sod? Yes No Type of sod Needed: _____

Comments: Tree is marked with flagging tape.

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

S.L.
Approved by: _____ Date: _____
County Representative

Work Completed and OK to Pay: Yes <input type="checkbox"/> No <input type="checkbox"/>	
Inspected by: _____	Date: _____
Invoice # _____	

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.
Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888

Request Details Report

Request Number
MA3-10849-R

Associated Work Order

Observed Date/Time
6/10/13 10:15:A

Citizen Information

Name Cait Dyson

Phone (352) 874-8749 Ext.

Address 25725
Colmar Av
Sorrento FL

Alternate Phone

Email Address

Organization

Requestor

Contact

Issue and Location

Activity

Issue

Tree Removal

Map Page

SEC TWN RNG

Address Number 27525

Route Colmar Av

Intersect Route Arlington Av (4388D)

Details

Citizen reports a dead tree in the ROW.

Notes

History

6/10/2013 Request has been printed and given to the Supervisor.

Wall, Treeva

6/11/2013 Contract tree removal requested.

Lee, Steven

Resolution _____

Request Response Date _____


Date _____

Time Arrived _____

Time Departed _____






LC-S-049



MOUNT PLYMOUTH LAKE

BOOK

-  Bridge
-  Signal



Maint Area



Sections

24	19	20	21
25	30	29	28
36	31	32	33

T19S - R28E

Map Page

19b-2930

Page

235



