



LAKE COUNTY
FLORIDA

To: _____ From: **Public Works/Road Ops**

Fax: _____ Pages: **1**

Phone: _____ Date: **7/3/2013**

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Westland Rd Segment No.: 3-4465A-01

Nearest City: Mount Dora

Address: 2315

Section 25 Township: 19 Range: 26

Description of Tree: pine

Location of Tree: at address

Size of tree (s): 27"

Grind Stump? yes Remove Stump? _____

If trim what class? Class 1 Class 2 Class 3

Power Lines or other hazards involved? Yes No

Sod? Yes No Type of sod Needed: _____

Comments: Tree is marked with orange flagging tape. Tree is green, but its roots are creating a safety hazard by lifting the sidewalk. Please grind roots underneath the sidewalk. Maintenance Area will replace the sidewalk after the tree is removed.

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

S.L.

Approved by: _____ Date: _____

County Representative

Work Completed and OK to Pay: Yes <input type="checkbox"/> No <input type="checkbox"/>	
Inspected by: _____	Date: _____
Invoice # _____	

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.
Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888

Request Details Report

Request Number
MA3-11045-R

Associated Work Order

Observed Date/Time
7/2/13 11:58:A

Citizen Information

Name Rita Wynn

Phone (352) 988-3006 Ext.

Address 2315
Westland Rd (4465A)
Mount Dora FL

Alternate Phone

Email Address

Organization

Requestor

Contact

Issue and Location

Activity

Issue

Sidewalk

Map Page

SEC TWN RNG

Address Number 2315

Route Westland Rd (4465A)

Intersect Route

Details

Citizen is calling on behalf of her daughter, who owns the reference property. She says that that there is a tree, whose roots are lifting the sidewalk.

Notes

History

7/2/2013	Request has been printed and given to the Supervisor.	Wall, Treeva
7/3/2013	Contract tree removal requested.	Lee, Steven

Resolution _____

Request Response Date _____

Date _____

Time Arrived _____

Time Departed _____









Click here to change page title



#	Alt Key	Owner	Parcel Address	Owner Address	Tools
1	1669120	CRITTENDEN KATHERINE & CORY	2315 WESTLAND RD MOUNT DORA FL 32757	2315 WESTLAND RD MOUNT DORA, FL 32757	Zoom In

25
19
26
seg 01