



LAKE COUNTY
FLORIDA

To: **Absolute Line Technologies** From **Public Works Road Ops**
E-mail: Phone: **(352) 343-6439**
Fax: **383-8085** Page: **1**
Phone: **383-0002** Date: **4/11/2013**
Pipe Cleaning & Video, 10-0609

WORK REQUEST

Date of Video and/or Report Due: ASAP
Road Name: Heather St Address: N/A
Segment Number: 3-4480B-04
Section: 28 Township: 19 Range: 27
Location: Under Heather St at intersection with Cherry Ln
Description of work to be performed: Clean pipe.
Pipe Size: 18 in
Percentage of pipe blocked: 10% or less 11% - 30% above 30%
Pipe Length: 39 ft Number of Man holes: 0
Clean only: TV only: Cleaning/TV:
Total footage for this request: 39 ft

If there are questions concerning pipe size(s), length(s) or the % of blockage shall be addressed and agreed upon in writing by the County Representative prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Request Details Report

Request Number MA3-10635-R Associated Work Order MA3-17304-WO Observed Date/Time 4/10/13 2:33:P

Citizen Information

Name _____ Phone _____ Ext. _____
Address _____ Alternate Phone _____
Email Address _____

Organization Storm Water
Requestor Lake County Public Works
Contact McArdle, Heath

Issue and Location

Activity _____ Issue Map Page 223 Drainage SEC 28 TWN 19 RNG 27

Address Number

Route Heather St (4480B)

Intersect Route

Details

Stormwater Inspection report dated 06/26/12:

Concrete pipe end @ low area on East side of Heather Street just North of Cherry Ln. DBI with grate on W side of Heather St appears to equalize low areas via pipe. Pipe appears to be full of debris.

Notes

History

4/10/2013 Request has been printed and given to the Supervisor. Wall, Treeva

Resolution CLEANED CULVERT PIPE ^{opening} AND
CLEANED OUT CATCH BASIN

Request Response Date 04/10/2013
Date _____
Time Arrived _____
Time Departed _____

STARTED
4-10-13
HENDERSON
CRITES
BOYD
CURRY

* NEEDS PIPE
CLEANED OUT
FULL OF DIRT
39" x 18"



Lake County Road Operations
May 2008 Edition

MAINTENANCE AREA 3 ASSET BC

- County Segments
- Guardrails
- Township - Range
- Signs
- Sections
- Streets

Daily Report Of Inspection



LAKE COUNTY FLORIDA

Location: HEATHER STREET (1180)

Project: _____

Well No.: CG 3-2472-0 City: MT. DORA

Date/Day Of Week: 06/26/2012 TUESDAY

Weather Conditions: Clear Partly Cloudy Heavy Clouds Fog

Temperature: High: 87 Low: 72

Wind: None Slight Strong

Rain: None Light Showers Heavy

Rain Duration: 0-2 Hrs. 2-4 Hrs. 4-6 Hrs. All Day

Working Conditions: Excellent Good Fair Poor Bad

Duration of Acceptable Conditions: All Day 4-6 Hrs. 2-4 Hrs. 0-2 Hrs. Unacceptable All Day

Soil Conditions: Dry Wet Extremely Wet

Comments:
28° 48.738' N CONCRETE PIPE END @ LOW AREA ON EAST SIDE
- 81° 37.108' W OF HEATHER STREET JUST NORTH OF CHERRY LANE.
DBI WITH GRATE ON WEST SIDE OF HEATHER
STREET APPEARS TO EQUALIZE LOW AREAS VIA
PIPE. PIPE APPEARS TO BE FULL OF DEBRIS.

Inspector's Name: (Printed) HEATH M. MCARDLE
Inspector's Signature: [Signature]

Hours on the Job: _____ Total Hours: _____
From: 11:15 To: 11:30 0.25
Page: 1 Of 1





Lake County Public Works

Daily Activity Worksheet

APR 11 2013

CH

Admin	<input type="checkbox"/>
MA I	<input type="checkbox"/>
MA II	<input type="checkbox"/>
MA III	<input checked="" type="checkbox"/>
Spec Proj	<input type="checkbox"/>
Traffic Ops	<input type="checkbox"/>

IS FEMA:

WO Number: MA3-17304-wo

STATUS: IN PROGRESS / COMPLETE

Assoc Request: MA3-10635-R

DATE: 4-10-13

TIME A: 1:00pm TIME D: 2:00pm

PROBLEM: _____

ADDRESS OR INTERSECTION: _____

SOLUTION: _____

LABOR

Emp Name (Labor ID)	Activity (include WOWR# if different from above)	Std Hrs	OT Hrs	SOT Hrs
HENDERSON	DRN CULVERT CLEANING	1		
BOYD	" " "	1		
CRITES	" " "	1		
CURRY	" " "	1		
TOTAL HOURS		4		

ASSETS

Asset ID (Road # or MSAG#)	Description	Activity
4480B-1	HEATHER ST	DRN CULVERT CLEANING

EQUIPMENT

Equip ID (Property No.)	Description	Operator:	Activity	HRS
21981	FIATBOB	HENDERSON	DRN CULVERT CLEANING	1

MATERIAL

Material ID (Description)	Unit	Qty