


| 10: | From: Pub | <u>IIC Works/Road Ops</u> |
|---|---|---|
| Fax: | Pages: | 1 |
| Phone: | Date: | 8/1/2013 |
| E-Mail: | | |
| TREE REMOVAL REQUEST | Γ | |
| Road Name: CR 44A/Rose St Series Nearest City:Umatilla Address: 39257 Section 18 Township: 18 Description of Tree: oak Location of Tree: 19' from edge of Size of tree (s): 51" Grind Stump? yes Remove Sture If trim what class? Class 1 Power Lines or other hazards invested? Yes No | Range: 27 of pavement mp? Class 2 Class 2 Colved? Yes | Class 3 |
| Comments: Tree is marked with | flagging tape | <u>5</u> . |
| or designee prior to the performance of the | work. Any work | eed upon in writing by either the Project Manager performed without agreement by all parties shall be ract. Invoices should be sent to the address listed |
| Approved by: | Date: | |
| County Representation | <u>tive</u> | |
| Work Completed and OK to | Pay: Yes | No |
| Inspected by: | | Date: |
| Invoice # | | |

Request Details Report

| Request Number As MA3-11178-R | avido con servicio | | /Time A |
|--|------------------------------------|------|---------------------------|
| Citizen Information Name Anonymous Address Not Provided (00) | Phone Alternate P Email Addr | hone | ext. |
| Organization Requestor | | | |
| Contact | | | |
| Issue and Location Activity | Issue Map Pag | | moval FWN RNG 18 27 |
| Address Number 39257 | | | |
| Route CR 44A/Rose St (73) | 75) | | |
| Intersect Route Skyline Details Citizen reports a dead tree. | Or (7773) | Sec. | ** |
| Notes | | | |
| History | | | |
| Resolution | | | |
| | 0012 | | |
| Request Response Date 08/01/2 | 2013 | | |
| | | | |
| The December | | | |





MAINTENANCE AREA 3 ASSET BO

Lake County Road Operations May 2008 Edition





